

Final Reclamation Inspection

October 05, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 305703

Inspection Document #: 708000185

Weld County, CO

NWNW Section 5 2N65W 6

Kasen Huwa
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: B & M *11-5
Location ID: 305703



Photo 1. Google Earth aerial imagery taken 5/2018 during active operations. Photo illustrates the well location (red circle), tank battery (red square), and well location access road (white arrow).

Inspection Photos
Location Name: B & M *11-5
Location ID: 305703



Photo 2. COGCC Online Map aerial imagery 2019 with related well (red dot), subject well (blue dot), tank battery (near southwest corner) and flowlines (black lines).

N →



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle) and flowlines (red lines). Tank Battery is addressed in Location 305179 report.

Inspection Photos
Location Name: B & M *11-5
Location ID: 305703



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle). Area has sparse crop coverage.