

Inspection Photos

February 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334631

Location Name: HMU-67S93W/16NWNE

Inspection Document #: 702801289

Garfield County, CO

NWNE Section 16 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HMU-67S93W/16NWNE
Location ID: 334631



Photo 1. Photos show production areas. A tank battery sign is absent (left).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801289

Inspection Photos
Location Name: HMU-67S93W/16NWNE
Location ID: 334631



Photo 2. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801289

Inspection Photos
Location Name: HMU-67S93W/16NWNE
Location ID: 334631



Photo 3. Photo shows an example of interim areas. Deep snow completely obscured vegetation.

