

| | | |
|---|---|---|
| <p>Project Name: C15W Assessment</p> | <p>Site Location: Garfield County, CO</p> | <p>Project Number: 022-147</p> |
| <p>Facility: C15W Spill Area</p> <p>Description: C15W Spill Discovery</p> |  A photograph showing a spill area. In the foreground, there is a large pile of grey gravel. To the right, a green metal structure, possibly a spill containment berm or part of a spill kit, is visible. The background shows a dry, hilly landscape under a blue sky with scattered white clouds. A shadow of the person taking the photo is cast on the gravel. | |
| <p>Facility: C15W Spill Area</p> <p>Description: C15W Excavation</p> |  A photograph of an excavation site. A large, dark pipe is visible, partially buried in the earth. A yellow surveying rod with black markings is positioned vertically on the right side of the excavation. A yellow caution tape with the text "CAUTION BELOW" is stretched across the bottom of the excavation. The soil is reddish-brown and appears to be a mix of dirt and rock. | |

| | | |
|--|--|---|
| <p>Project Name: C15W Assessment</p> | <p>Site Location: Garfield County, CO</p> | <p>Project Number: 022-147</p> |
| <p>Facility: C15W Spill Area</p> <p>Description: C15W Excavation</p> |  | |
| <p>Facility: C15W Spill Area</p> <p>Description: C15W Excavation</p> |  | |