

Inspection Photos

API: 071-09351

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/27/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09351 | Date: 3/27/2023

Inspection Photos



Photo 1. Facing south along the access road. There was heavy equipment being used at an nearby location which is the reason for the disturbance of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09351 | Date: 3/27/2023

Inspection Photos



Photo 2. Facing east at the same point in the road as previous photo. There is a cement culvert pushed into the erosion embankment which needs to be removed and the embankment needs to be stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09351 | Date: 3/27/2023

Inspection Photos



Photo 3. Facing northeast at the same area of the road as previous photos. This culvert outlet has eroded and needs to be repaired along with outlet protection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09351 | Date: 3/27/2023

Inspection Photos



Photo 4. Facing northeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09351 | Date: 3/27/2023

Inspection Photos



Photo 5. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09351 | Date: 3/27/2023