

Final Reclamation and Stormwater Inspection

Date: 04/14/2023

Operator: 8 NORTH LLC - 10575

Location ID: 459183

Inspection Document #: 708200142

Weld County, CO

NWNW Section 34 T10N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Ivan 34-A Pad
Location ID: 459183



Photo 1. Facing north. Operator submitted Form 4 Sundry Notices stating the above wells were not drilled. The Form 2A (Doc #401530837) expired on 11/20/2021. Location was not constructed at the proposed well locations based off field observations. No oil and Gas activities observed.

Inspection Photos
Location Name: Ivan 34-A Pad
Location ID: 459183



Photo 2. Facing east; see comments in Photo 1.

Inspection Photos
Location Name: Ivan 34-A Pad
Location ID: 459183



Photo 3. Facing south; see comments in Photo 1.

Inspection Photos
Location Name: Ivan 34-A Pad
Location ID: 459183



Photo 4. Facing west; see comments in Photo 1.