

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 413-27 Pad

Location ID: 335479



Apr 20, 2023 at 11:11:58 AM



Apr 20, 2023 at 11:12:01 AM

Photo # 5935 From entrance to location

Photo # 5936 From entrance to location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 413-27 Pad

Location ID: 335479



Photo # 5937 Location



Photo # 5938 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 413-27 Pad

Location ID: 335479



Photo # 5939 Location



Photo # 5952 Meter calibration info not conspicuously posted



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 413-27 Pad

Location ID: 335479



Photo # 5953 Meter calibration info not conspicuously posted



Photo # 5940 Stained soils & gravel

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC RWF 413-27 Pad
Location ID: 335479



Photo # 5943 Debris



Photo # 5945 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 413-27 Pad

Location ID: 335479



Photo # 5951 Debris



Photo # 5956 Debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 413-27 Pad

Location ID: 335479



Photo # 5955 Containment liner needs maintenance



Photo # 5957 Erosion & transport of sediment



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 413-27 Pad

Location ID: 335479



Photo # 5958 Erosion & transport of sediment



Photo # 5960 Erosion & transport of sediment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 413-27 Pad

Location ID: 335479



Photo # 5961 Erosion & transport of sediment