

Inspection Photos

May 17, 2023

Operator: GRMR OIL & GAS LLC - #10524

Location ID: 413919

Location Name: DURHAM/4-31

Inspection Document #: 702801543

Moffat County, CO

NESE Section 31 T5N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DURHAM/4-31
Location ID: 413919



Photo 1. Photo taken from the north shows an overview of the location including interim areas in the foreground.



Inspection Photos
Location Name: DURHAM/4-31
Location ID: 413919



Photo 2. Photos show unmarked anchors.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801543