

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1596 From entrance to location



Photo # 1597 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1598 Location



Photo # 1599 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1600 Location



Photo # 1622 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1609 Holes in containment liner/liner needs maintenance



Photo # 1610 Holes in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1611 Hole in containment liner/liner needs maintenance



Photo # 1612 Hole in containment liner/liner needs maintenance



Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1613 Holes in containment liner/liner needs maintenance



Photo # 1614 Holes in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1615 Holes in containment liner/liner needs maintenance



Photo # 1616 Hole in containment liner/liner needs maintenance



Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1617 Hole in containment liner/liner needs maintenance



Photo # 1618 Holes in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979




Photo # 1619 Holes in containment liner/liner needs maintenance



Photo # 1620 Holes in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1621 Hole in containment liner/liner needs maintenance



Photo # 1624 Debris

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1625 Hole in containment liner/liner needs maintenance



Photo # 1626 Hole in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1627 Holes in containment liner/liner needs maintenance



Photo # 1628 Holes in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1629 Holes in containment liner/liner needs maintenance



Photo # 1630 Holes in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1631 Holes in containment liner/liner needs maintenance



Photo # 1632 Holes in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1633 Hole in containment liner/liner needs maintenance



Photo # 1634 Hole in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1635 Hole in containment liner/liner needs maintenance



Photo # 1636 Hole in containment liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC A18E Pad
Location ID: 323979



Photo # 1637 Holes in containment liner/liner needs maintenance



Photo # 1638 Holes in containment liner/liner needs maintenance