

Final Reclamation and Stormwater Inspection

Date: 07/19/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 326968

Inspection Document #: 708200395

Weld County, CO

SWNE Section 3 T8N R58W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: Lilli Unit 7-3
Location ID: 326968



Photo 1. Facing west from the location. The access road will need to be reclaimed.

Inspection Photos
Location Name: Lilli Unit 7-3
Location ID: 326968



Photo 2. Taken from the southwest corner of the location. Undesirable vegetation (e.g. CO List C Noxious weed- cheatgrass) infestations were observed through the location and do not appear to have been managed for with evidence of plants seeding out. This species requires management in both county and state regulations.

Inspection Photos
Location Name: Lilli Unit 7-3
Location ID: 326968



Photo 3. Facing east from the entrance; see comments in Photo 2.

Inspection Photos
Location Name: Lilli Unit 7-3
Location ID: 326968



Photo 4. Center portion of the location; see comments in Photo 2.

Inspection Photos
Location Name: Lilli Unit 7-3
Location ID: 326968



Photo 5. Pipe risers remain on location; this equipment was documented in previous inspections (dating back to 07/31/2017; Doc #675103782) and has yet to be removed. All equipment must be removed from the abandoned location.

Inspection Photos
Location Name: Lilli Unit 7-3
Location ID: 326968



Photo 6. Debris observed on the outside of the location perimeter fencing will require removal.