

Inspection Photos
Location Name: HSR-Strear 14-10A
Location ID: 330972



Photo 1 2 track road to location overgrown with undesirable vegetation.



Photo 2 Location ROW overgrown with undesirable vegetation.

Inspection Photos
Location Name: HSR-Strear 14-10A
Location ID: 330972



Photo 3 WH/sign undesirable vegetation growing inside WH fencing.