

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/36NWSW

Location ID: 335253

Date: 8/23/2023



North Entrance to Location – Photo #06064



Wellhead – Photo #06069

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/36NWSW

Location ID: 335253

Date: 8/23/2023



Separator – Photo #06065



Tank Battery – Photo #06068

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BARRETT ET AL-66S96W/36NWSW

Location ID: 335253

Date: 8/23/2023



Insufficient Erosion Control Near Tank Battery – Photo
#06066



Insufficient Erosion Control Near Tank Battery – Photo
#06067