

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION Receive Date: 09/07/2023 Document Number: 403522722

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 10779 Contact Person: Spencer Jackson Company Name: SCOUT ENERGY MANAGEMENT LLC Phone: (972) 965-5580 Address: 13800 MONTFORT DRIVE SUITE 100 Fax: () City: DALLAS State: TX Zip: 75240 Email: spencer.jackson@scoutep.com

Identification Information

API Number: 05 - - OGCC Facility ID: 117387 Initial Form 19 or 27 Document number: Facility Name: Collection Station 16 Facility Number: Facility Type: PIT Location QtrQtr: SWSE Section: 20 Township: 2N Range: 102W Meridian: 6 County: RIO BLANCO Field Name: RANGELY Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: SCOUT ENERGY MANAGEMENT LLC Agent Name: Spencer Jackson Title: Senior Remediation Specialist Phone Number: 972-965-5580 Email: spencer.jackson@scoutep.com

Rule 909.J Inspection Information

Date the Pit was Inspected 06/22/2023 On inspection the Pit was: [X] Unlined [] Lined [] Fenced [] Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 117387 Facility Name: Collection Station 16 Facility Type: PIT Location: QtrQtr: SWSE Sec: 20 Twp: 2N Range: 102W Meridian: 6 County Name: RIO BLANCO Latitude: 40.122235 Longitude: -108.869188

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 112724 Document Name: Collection Station #16-TENORM Analysis File Name: R-CS16-G-1-062123-117387.xlsx Sample Type: Matrix: Facility ID: 117387 Sample ID: 651539 Sample Name: Collection Station 16-TENORM Analysis Sample Date: 06/21/2023 Collection Point: SEP Matrix: WATER Pre Post: Rule 909.j initial sample Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Pace Analytical Lab Sample ID: L1628922-10

Batch ID: 112723	Document Name: Collection Station #16- Chemical Analysis	File Name: R-CS16-G-1-062123.xlsx
SampleType: _____	Matrix: _____	
Facility ID: 117387	Sample ID: 651538	Sample Name: Collection Station 16-Chemical Analysis
Collection Point: SEP	Matrix: WATER	Pre Post: Rule 909.j initial sample
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Pace Analytical
		NOAV Number: _____
		Lab Sample ID: L1628917-10

Sample Facility Attachment:

No Facility Attachment

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through the COGIS data system.	09/07/2023
Total: 1 comment(s)		