

Interim and Stormwater Inspection

September 4th, 2023

Operator: Simcoe LLC - 10749

Location ID: 311996

Inspection Document #: 714000015

La Plata County, CO

Township: NESE 21 34N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Groff A #4, 2
Location ID: 311996



Photo 1. Overview photo of the disturbance taken from the well pad entrance. Note 2 wells shared this disturbance.



API #: 067-09434, 08364



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Groff A #4, 2
Location ID: 311996



9/4/23
+37.173482,-107.825428
353° N

Photo 2. Eastern edge of the disturbance taken from the southern edge.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09434, 08364

Inspection Photos
Location Name: Groff A #4, 2
Location ID: 311996



Photo 3. Northern edge of the disturbance taken from the eastern edge.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09434, 08364

Inspection Photos
Location Name: Groff A #4, 2
Location ID: 311996



Photo 4. Western edge of the disturbance taken from the northern edge.

Inspection Photos
Location Name: Groff A #4, 2
Location ID: 311996



Photo 5. Barbed wire fence surrounding disturbance is broken allowing cattle to graze within the disturbance.