

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/10/2023

Submitted Date:

10/20/2023

Document Number:

701007508**FIELD INSPECTION FORM**Loc ID 303377 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 97120Name of Operator: WISE\* WAYNE LAddress: P O BOX 5116City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wise, Wayne		wwise@peakviewenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253011	WELL	PR	12/01/2020	GW	125-06888	ALICE WELP 1-10	PR

**General Comment:**[P&A Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Trail through CRP		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Wire panels around wellhead		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	Meter run is 1245' southwest of wellhead next to Allison 1-9 meter shed		
Corrective Action:	Remove equipment and begin final reclamation process		Date: 11/20/2023
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 50% buried by meter shed		
Corrective Action:	Remove equipment and begin final reclamation process		Date: 11/20/2023

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 253011 Type: WELL API Number: 125-06888 Status: PR Insp. Status: PR**Cement**Cement ContractorContractor Name: Excel Well Service

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 2200/1750/456Cement Volume (sx): 96 SXS

Good Return During Job: \_\_\_\_\_

Cement Type: NeatComment:

LOG TECH WIRELINE, EXCEL WELL SERVICE. MIRU LOGTECH, RIH W/CIPB TO 2200', BALE DUMP 2 SXS ON TOP. RIH W/CIBP TO 1750', BALE DUMP 2 SXS CMT ON TOP. RIH W/GUN, PERF @ 456'. MIRU EXCEL, PUMP PUMP 37BBLs WATER TO BREAK CIRC, PUMP 96 SXS W/CMT TO SFC.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Location and access are grassed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT