

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/16-9

Location ID: 334717

Date: 10/30/2023



Entrance to Location – Photo #07220



NW Corner of Location – Photo #07221



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/16-9

Location ID: 334717

Date: 10/30/2023



Wellheads – Photo #07222



Separators – Photo #07225

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/16-9

Location ID: 334717

Date: 10/30/2023



Tank Battery – Photo #07228



Unsecured Hatch on Separator – Photo #07226



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, MV/16-9

Location ID: 334717

Date: 10/30/2023



**Lack of Stabilization – Photo #07224**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #07231**