

Operator: EXTRACTION OIL & GAS INC
Location Name: BECKY-62N69W 36NWSE
Loc ID: 321348
Inspection: 702402334



Exhibit A

CA: Undesirable vegetation growing tall along access road, around WH ROW & unused transformers. Comply with Rule 606.

CA Resolution: Overgrowth around the Wellhead and access road has been addressed and mowed to comply with Rule 606.