

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-14 Pad**  
**Location ID: 335065**



**Location Overview: Location is within High Priority/Density  
Habitat areas & in close proximity to Bald Eagle Roost Sites.**

**Section/Township/Range: 14 6S94W**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-14 Pad**  
**Location ID: 335065**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-14 Pad**  
**Location ID: 335065**



**Photo # 6550 Stockpiled soils/sediment choking off vegetation**



**Photo # 6551 Stockpiled soils/sediment choking off vegetation**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-14 Pad**  
**Location ID: 335065**



**Photo # 6552 Stockpiled soils/sediment choking off vegetation**



**Photo # 6553 Stockpiled soils/sediment choking off vegetation**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-14 Pad**  
**Location ID: 335065**



**Photo # 6554 Failure to minimize surface disturbance**



**Photo # 6555 Failure to minimize surface disturbance**