

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-14 Pad

Location ID: 335065



Photo # 6540 From entrance to location



Photo # 6541 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-14 Pad

Location ID: 335065




Photo # 6542 Location

Photo # 6543 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-14 Pad

Location ID: 335065



Nov 14, 2023 at 11:15:47 AM
CO



Nov 14, 2023 at 11:16:06 AM
CO

Photo # 6544 Location

Photo # 6545 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-14 Pad

Location ID: 335065



Photo # 6546 Location

Photo # 6547 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 434-14 Pad

Location ID: 335065



Photo # 6548 Debris

Photo # 6549 Stained soils & gravel