



**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                        | #   |       | corrective date |
|-----------------------------|-----|-------|-----------------|
| Gas Meter Run               | # 1 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |
| Horizontal Heated Separator | # 2 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |
| Bird Protectors             | # 4 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |
| Emission Control Device     | # 2 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type        | Tank ID | SE GPS |
|--------------------|---|----------|-------------|---------|--------|
| PRODUCED WATER     | 1 | OTHER    | BV CONCRETE |         | ,      |
| Comment:           |   |          |             |         |        |
| Corrective Action: |   |          |             | Date:   |        |

**Paint**

|                 |                      |
|-----------------|----------------------|
| Condition       | <input type="text"/> |
| Other (Content) | <input type="text"/> |

|                          |  |
|--------------------------|--|
| Other (Capacity) 60 BBLs |  |
| Other (Type)             |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
|                    |          |                     |                     |             |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 2 | 300 BBLs | STEEL AST |         | 40.319600,-104.520100 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         |                       |
|                    |   |          |           |         | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  |       |
|                    |    |  | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: |       |
|                    | Date: |

**Inspected Facilities**

Facility ID: 447335 Type: TANK API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: [active tank battery](#)

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 699107895    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6336125">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6336125</a> |