

Inspection Photos
Location Name: HOWLAND#2
Location ID: 320089



Photo#1 Compressor



Photo#2 CA: Trash and debris

Inspection Photos
Location Name: HOWLAND#2
Location ID: 320089




Photo#3 CA: Trash and debris



Photo#4 Separator

Inspection Photos
Location Name: HOWLAND#2
Location ID: 320089



Photo#5 Pumpjack



Photo#6 CA: No secondary containment for barrel

Inspection Photos
Location Name: HOWLAND#2
Location ID: 320089



Photo#7 Production Tank and Produced Water Tank