


Inspection Photos
Location Name: BRADBURY 32-24
Location ID: 320178



Photo#1 Production Tank

Photo#2 CA:No bullplug

Inspection Photos
Location Name: BRADBURY 32-24
Location ID: 320178



Photo#3 CA:No bullplug

Photo#4 CA:No labels or markers

Inspection Photos
Location Name: BRADBURY 32-24
Location ID: 320178



Photo#5 Separator

Photo#6 Pumpjack

Inspection Photos
Location Name: BRADBURY 32-24
Location ID: 320178



Photo#7 CA: Unused Equipment

Photo#8 CA: Unused Equipment