

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Crow Valley 7-62-32 1M

Loc ID: 422253

Inspection: 696305496



Exhibit A



Exhibit B

CA: Unused Pipe at Well Site; see photos. Comply with Rule 606.

CA Resolution: Operator has reported that all identified/unused pipe have been appropriately removed from the location to comply with Rule 606.

CA: Tumbleweed Debris at Wellhead; see photos. Comply with Rule 606.

CA Resolution: Operator has reported that tumbleweed debris at the Wellhead has been cleared/removed to comply with Rule 606.