

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, MURRAY-68S96W/1SWSW

Location ID: 334182

Date: 12/20/2023



Dec 20, 2023 at 11:21:12  
5201-5757 County Road 306  
Parachute CO 81635  
United States



Dec 20, 2023 at 11:23:34  
5201-5757 County Road 306  
Parachute CO 81635  
United States

Location Entrance – Photo #08316

Separators – Photo #08320



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, MURRAY-68S96W/1SWSW

Location ID: 334182

Date: 12/20/2023



**Tank Battery – Photo #08317**



**Lack of Stabilization – Photo #08322**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, MURRAY-68S96W/1SWSW

Location ID: 334182

Date: 12/20/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit**  
– Photo #08323