

**Operator: HIGHPOINT OPERATING CORPORATION**

**Location Name: Pappenheim 6-62-23 Pad**

**Loc ID: 432757**

**Inspection: 696305499**



**Exhibit A**



**Exhibit B**

**CA:** Container at 6-62-23-0164CDH Pumping Unit missing Content Labels. See photos. Install sign to comply with Rule 605.h.

**CA Resolution:** Operator has appropriately installed content signage to comply with Rule 605.h.

**CA:** Stained Soil at VRU. See photos. For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

**CA Resolution:** Operator has cleared and properly disposed of identified stained soil to comply with Rule 905.e.

**CA:** Tumbleweed Debris build-up at 6-62-23-0164CDH Pumping Unit. Comply with Rule 606.

**CA Resolution:** Operator has cleared tumbleweed debris and trash from the location to comply with Rule 606.



Exhibit A



Exhibit B



Exhibit C



**Exhibit D**

**CA:** Unmarked OOSLAT Risers at various Locations on Pad - 2" Risers west of Pumping Unit, 1" Risers at VRU, 2" buried Bull Plugs at Heater Treater. See photos. Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

**CA Resolution:** Operator has appropriately marked identified risers and exposed bull plugs at Heater Treater to comply with Rule 1105.