

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE M16 595 Pad

Location #: 311634



Photo # 804 From entrance to location



Photo # 805 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE M16 595 Pad

Location #: 311634



Dec 26, 2023 at 12:21:58 PM
CO

Photo # 806 Location



Dec 26, 2023 at 12:26:51 PM

Photo # 807 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE M16 595 Pad

Location #: 311634



Photo # 808 Production tank labeling contains inaccurate /incorrect information




Photo # 809 Tank battery lacks signage

Inspection Photos

Location Name: CAERUS PICEANCE LLC LONG RIDGE M16 595 Pad

Location #: 311634



**Photo # 810 Wellhead sign not conspicuously located
/appears to be buried in snow**