

Inspection Photos

12/27/2023

Operator: CAERUS PICEANCE LLC #10456

Location ID: 334736

Inspection Doc: 696205496

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334736



Photo 1: Photos taken from the north end of the working pad surface. Photos provide an overview of the Location from northeast, southeast, south to southwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334736



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334736



Photo 3: Photo example showing cellars at wells remain open. .



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334736



Photo 4: Photos examples showing interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources