

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/29-09 Pad

Location ID: 334426

Date: 1/3/2024



Location Entrance – Photo #08471



Wellheads – Photo #08475

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/29-09 Pad

Location ID: 334426

Date: 1/3/2024



Wellheads – Photo #08476



Separators – Photo #08474



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/29-09 Pad

Location ID: 334426

Date: 1/3/2024



Jan 3, 2024 at 14:20:15



Jan 3, 2024 at 14:27:31

Separators – Photo #08472

Tank Battery – Photo #08478

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/29-09 Pad

Location ID: 334426

Date: 1/3/2024



Stored Equipment – Photo #08479



Lack of Stabilization – Photo #08473

Inspection Photos

Location Name: LARAMIE ENERGY LLC, Gunderson/29-09 Pad

Location ID: 334426

Date: 1/3/2024



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08481