

Inspection Photos
Location Name: Wells Ranch USX AE 31-11P
Location ID: 310822



Photo 1 – Wellhead Sign



Photo 2 – Wellhead – Tumbleweeds

Inspection Photos
Location Name: Wells Ranch USX AE 31-11P
Location ID: 310822



Photo 3 – Unmarked Riser

Photo 4 – Wellhead Tag – NEWS

Inspection Photos
Location Name: Wells Ranch USX AE 31-11P
Location ID: 310822



Photo 5 – Wellhead Tag – TA



Photo 6 – Wellhead – Tumbleweeds