

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

03/04/2024

Document Number:

403706335

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: <u>47120</u>	Contact Person: <u>Dane Olson</u>
Company Name: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Phone: <u>(307) 760-5319</u>
Address: <u>P O BOX 173779</u>	Fax: <u>()</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>	Email: <u>Dane_Olson@oxy.com</u>

Identification Information

API Number: <u>05 - 123-18819</u>	OGCC Facility ID: <u>251016</u>	Initial Form 19 or 27 Document number: _____
Facility Name: <u>HSR-DAVIS, V.</u>	Facility Number: <u>6-26</u>	Facility Type: <u>WELL</u>
Location QtrQtr: <u>SENW</u>	Section: <u>26</u>	Township: <u>3N</u>
	Range: <u>67W</u>	Meridian: <u>6</u>
County: <u>WELD</u>	Field Name: <u>WATTENBERG</u>	
Federal, Indian or State Lease Number: _____		

Information Submitted By:

Company Name: <u>Absaroka Solutions</u>	Agent Name: <u>Jordan Fleming</u>	Title: <u>Environmental Professional</u>
Phone Number: <u>7202448469</u>	Email: <u>jordan.fleming@absarokasolutions.com</u>	

Rule 909.J Inspection Information

Date the Pit was Inspected _____

On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: <u>251016</u>	Facility Name: <u>HSR-DAVIS, V. 6-26</u>	Facility Type: _____
Location: QtrQtr: <u>SENW</u>	Sec: <u>26</u>	Twp: <u>3N</u>
	Range: <u>67W</u>	Meridian: <u>6</u>
County Name: <u>WELD</u>	Latitude: <u>40.198703</u>	Longitude: <u>-104.859683</u>

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: <u>117633</u>	Document Name: <u>Size of file in bytes: 32256</u>	File Name: <u>2023_12_11_BW_05_123_18819_BHD_SGS_ECM C.xls</u>
SampleType: _____	Matrix: _____	
Facility ID: <u>251016</u>	Sample ID: <u>657006</u>	Sample Name: <u>BW_05_123_18819_BHD</u>
	Sample Date: <u>12/11/2023</u>	
Collection Point: <u>BDH</u>	Matrix: <u>WATER</u>	Pre Post: <u>Bradenhead Water Sample</u>
Project Number: _____	Remediation Number: _____	Complaint Number: _____
		NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: <u>Accutest</u>
		Lab Sample ID: <u>DA60593-1</u>

Batch ID: 117634 Document Name: Size of file in bytes: 31232 File Name: 2023_12_11_BW_05_123_18819_BHD_Trip_Blank_SGS_ECMC.xls

SampleType: _____ Matrix: _____

Facility ID: 251016 Sample ID: 657007 Sample Name: BW_05_123_18819_BHD_TRIP_BLANK Sample Date: 12/11/2023

Collection Point: TB Matrix: WATER Pre Post: Trip Blank

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Accutest Lab Sample ID: DA60594-1

Batch ID: 117632 Document Name: Size of file in bytes: 36864 File Name: 2023_12_11_BW_05_123_18819_BHD_Isotech_NG_4_ECMC.xls

SampleType: _____ Matrix: _____

Facility ID: 251016 Sample ID: 657005 Sample Name: BW_05_123_18819_BHD Sample Date: 12/11/2023

Collection Point: BDH Matrix: GAS Pre Post: Bradenhead Water Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 902880

Batch ID: 117635 Document Name: Size of file in bytes: 34816 File Name: 2023_12_11_SP_05_123_18819_C_Isotech_NG4_E_CMC.xls

SampleType: _____ Matrix: _____

Facility ID: 251016 Sample ID: 657008 Sample Name: SP_05_123_18819_C Sample Date: 12/11/2023

Collection Point: PRDC Matrix: GAS Pre Post: Production Gas Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 902804

Batch ID: 117632 Document Name: Size of file in bytes: 36864 File Name: 2023_12_11_BW_05_123_18819_BHD_Isotech_NG_4_ECMC.xls

SampleType: _____ Matrix: _____

Facility ID: 251016 Sample ID: 657004 Sample Name: BW_05_123_18819_BHD Sample Date: 12/11/2023

Collection Point: BDH Matrix: GAS Pre Post: Bradenhead Water Sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: ISOTECH Lab Sample ID: 902880

Sample Facility Attachment:

No Facility Attachment

Sample COGCC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
657007	123-18819	HSR-DAVIS, V. 6-26	Trip Blank

General Comments

User Group	Comment	Comment Date
Engineer	The data submitted by the operator can be accessed through COGIS data system.	03/05/2024

Total: 1 comment(s)