



99999999

## WELL SITE INSPECTION FORM

SCANNED



WELL NAME Fassler 1-27  
OPERATOR Doherty, P.A.  
LOCATION NW SW 27-2N-53W  
FIELD \_\_\_\_\_

API NUMBER 05 - 121 - 10346  
PERMIT NUMBER \_\_\_\_\_  
COUNTY Washington  
INSPECTOR Binkley

## AL/PA/DA INSPECTION RESULTS:

PASS(Y) ✓ FAIL(N) \_\_\_\_\_ DATE 8-4-88 FN \_\_\_\_\_ FD ✓ WO \_\_\_\_\_

=====

DATE OF INSPECTION BEFORE/DURING DRILLING \_\_\_\_\_

CASING SIZE \_\_\_\_\_ DEPTH SET \_\_\_\_\_ CMT VOL \_\_\_\_\_ WOC \_\_\_\_\_  
CONSISTENT WITH APD CASING PROGRAM? \_\_\_\_\_ RETURNS \_\_\_\_\_  
RIG \_\_\_\_\_ BOP'S \_\_\_\_\_ CONTACT \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION \_\_\_\_\_

PIPE SET? \_\_\_\_\_ COMPLETION RIG/ACTIVITY \_\_\_\_\_

DRILLING PITS: CLOSED \_\_\_\_\_ OPEN \_\_\_\_\_ WELLHEAD SYSTEM INSTALLED \_\_\_\_\_

TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ WELL SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_

SKIM PIT: \_\_\_\_\_ gal TANKS: ( ) \_\_\_\_\_ bbls

EQUIPMENT \_\_\_\_\_

BRADENHEAD PRESSURE \_\_\_\_\_ FLUID: NO \_\_\_\_\_ YES \_\_\_\_\_ TYPE \_\_\_\_\_

METER RUN: YES \_\_\_\_\_ NO \_\_\_\_\_ WELL STATUS: PR \_\_\_\_\_ TA \_\_\_\_\_ SI \_\_\_\_\_ WELL CAT 3- \_\_\_\_\_

## AL/PA/DA INSPECTION

DATE PLUGGED: 10-8-87 DATE PERMIT EXPIRED: \_\_\_\_\_

HOLE PLUGGED: YES ✓ NO \_\_\_\_\_ PITS BACKFILLED: YES ✓ NO \_\_\_\_\_

MATERIAL BURIED: YES ✓ NO \_\_\_\_\_ NA \_\_\_\_\_ SITE CLEAN: YES ✓ NO \_\_\_\_\_

BOND RELEASE OK: YES ✓ NO \_\_\_\_\_ FED \_\_\_\_\_ HOLE MARKER: YES \_\_\_\_\_ NO ✓

DATE OF SAFETY/STATUS INSPECTION 8-4-88

COMMENTS Fred Fassler released.



00066558