

# Increase COGCC Setback Requirement

- Current regulations inadequate
- Poses undue risk to public health and safety
- Serious detrimental impact on quality of life
- Lowers property values



Home

Gas Well Operation

A photograph of a rural property. In the foreground, there is a dirt area with a green metal shed on the left. A white pipe is connected to the shed. To the right of the shed is a large pile of rocks and dirt. In the background, there is a dense forest of pine trees. A house with a blue roof is visible through the trees on the right side. The word "Home" is written in yellow text in the upper right area of the image.

Home

Noise level measured 60 dbA at this spot



Gas Well Operation

Home

# Would you want this in your front yard?



This production pit has not been used in years, yet remains open in violation of current COGCC regulations regarding interim reclamation.