




Kerr-McGee Oil & Gas Onshore LP  
1099 18<sup>th</sup> Street, Suite 1800  
Denver, Colorado 80202  
720-929-6000 Fax 720-929-7000

May 29, 2009

Mr. Robert Chesson  
Colorado Oil and Gas Conservation Commission  
1120 Lincoln Street, Suite 801  
Denver, CO 80203



**RE: 2008 Annual Project Summary Report  
Kerr-McGee Oil & Gas Onshore LP**

Dear Mr. Chesson:

Enclosed please find a copy of the 2008 Annual Project Summary Report. This 2008 Annual Project Summary Report consists of the Assessment/Remediation Project Inventory Table, which provides the individual site incident date, the Colorado Oil and Gas Conservation Commission (COGCC) Remediation Number, well name, site status, review of the groundwater analytical data with respect to the Colorado Groundwater Quality Standards (CGWQS) and recommendations for no further action (NFA), ongoing quarterly groundwater monitoring, groundwater monitoring well reduction and/or additional soil and groundwater assessment activities to be conducted during 2009. Site maps (Figure 1), groundwater analytical summary tables (Table 1) and where appropriate, soil and/or surface water analytical summary tables (Table 2) are also provided for each site.

A number of NFA requests have previously been submitted to the COGCC, and are awaiting approval. These sites show the groundwater benzene, toluene, ethylbenzene and xylenes (BTEX) concentrations to be below the CGWQS for four or more quarterly groundwater sampling events. The outstanding NFA request sites are listed below:

- ✓ • Ft. St. Vrain 3, 9/ PSC 14, 23-9, 14-9-5Y (Remediation # 3951) 2057612
- ✓ • Gladys Jaccardi #1, Moser 11,12,13-4 (Remediation # 3956) ✓
- ✓ • 16-411-8" Gathering Line (Remediation # 4394) — 1941268 ✓
- ✓ • Foster 1-22 (Remediation # 4397) — 1941439 ✓
- ✓ • Abbett Leonard G GU #1 (Remediation # 4360) 1984503 ✓
- ✓ • Norgren Donald "C" #1 (Remediation # 4353) 1984454 ✓

- ✓ • Schmidt CJ Unit 1 (Remediation # 4359) ✓ 198 4496
- ✓ • Warren Farms Inc "B" #2 (Remediation # 4357) ✓ 198 4480
- ✓ • Getz Helmer Unit True #1 (Remediation # 4450) 123-11203 [1943021]
- ✓ • Caminisch Phillip GU #1 (Remediation # 4422) 123-08600 [1942508]

Based on review of the 2008 Annual Project Summary Report, a number of sites warrant groundwater monitoring well reduction. These sites show the BTEX concentrations to be below the CGWQS for three or more quarterly groundwater sampling events in one or more groundwater monitoring wells. A list of the sites and associated groundwater monitoring wells that well reduction is being requested for are listed below:

- ✗ • Berry #1/ Kurtz #1 (Remediation # 474) 123-10411 8-3N-67W  
MW13R, MW15
- ~~• HSR-Gibler 11, 14-3A/PryMac GU No.1 (Remediation # 736) 3-2W-67W  
MW02 and MW06~~
- ✗ • HSR-Barron 15-35/ HSR-Davis 16-35/ HSR-Sharkey 8, 9-35 (Remediation # 1503)  
MW03, MW04 and MW12
- ✗ • Kelly Gas Unit #1, #2/ Cannon 1-18/ Cannon Land 7-18/ McPeck 3-18, 2-18A  
(Remediation # 1530)  
MW01, MW03 and MW08
- ~~• HSR-Guinan 9-15/ HSR-Wolf 10-15A (Remediation # 1618)  
MW03, MW06, MW07, MW08, MW09, MW10, MW12, MW13, MW14, MW15,  
MW16 and MW20~~
- ✗ • UPRR 62 Pan AM D #1/ Winden 12-15A (Remediation # 1730)  
MW05, MW08, MW13, MW14 and MW15
- ~~• HSR-Cahill 2-16/ HSR-Cantwell 7-16A (Remediation # 1731)  
MW12, MW15~~
- ~~• 16-10-075-18-4 Pipeline (Remediation # 3320)  
MW07, MW09 and MW12~~
- ~~• Sarchet #1 (Remediation # 3388)  
MW02, MW03, MW04, MW13 and MW14~~

~~• HSR-Brady 15-25/ HSR-Krandel 9-25 (Remediation # 3696)  
MW03, MW04, MW07, MW08, MW09, MW11, MW16 and MW17~~

~~• HSR-Blank 15-5/ HSR-Cabral 16-5 (Remediation # 3562)  
MW01~~

~~• Anderson 12-27/ Bohlender 1-27 (Remediation # 3559)  
MW01 and MW02~~

~~• Ione Land & Cattle UT 1/ Cannon Federal 11-8 (Remediation # 3679)  
MW01, MW07, MW09 and MW10~~

~~• John Martinez GU #1 (Remediation # 3644)  
MW05, MW06 and MW07~~

~~• Keith Carter GU #1 (Remediation # 3643)  
MW02, MW03 and MW05~~

~~• HSR-Jones 16-36 (Remediation # 3676)  
MW01, MW05, MW07, MW08 and MW09~~

~~• Nelson Milton H "I", "K", "L" #1 (Remediation # 3692)  
MW03 and MW14~~

~~• Hazel McHale B #1 (Remediation # 3732)  
MW04 and MW06~~

~~• James N. Mathisen B #2/ HSR-Myrna 15-12A (Remediation # 3953)  
MW06 and MW07~~

~~• UPRR 22 Pan Am "L" #1/ Barclay 31, 42-27 (Remediation # 4027)  
MW03, MW07, MW08, MW09, MW11, MW13~~

~~• HSR-Sharkey 15-2A/ Fort St Vrain 16 (Remediation # 4088)  
MW07 and MW08~~

~~• Barclay 12-27/ UPRR 22 Pan Am "C" #1 (Remediation # 4096)  
MW01, MW03, MW07, MW08, MW13 and MW19~~

~~• HSR-Joyce 11-27A/ HSR-Randall 13-27A/ HSR-Smythe 14-27 (Remediation # 4095)  
MW01 and MW05~~


- ~~Avery 10-27A, Savul 15-27, Tuteur 9-27A (Remediation # 4188)~~  
MW05 and MW09

Additionally, in the Form 27 submittal for the PL-14-10-075-1083-4 Pig Launch Station site, (SENE 1-T4N-R68W) we stated that we do not believe that our facilities are the source of the release. Therefore, we have ceased all assessment activities (including groundwater monitoring) at this site.

Feel free to contact me at 720-929-6726 if you have any questions regarding this information.

Sincerely,

Kerr-McGee Oil & Gas Onshore LP



Paul D. Schneider, P.G.  
Staff Environmental & Regulatory Analyst

Attachments