

Savage and Savage *Environmental*

practical solutions for environmental issues

4610 Haystack Drive
Windsor, Colorado 80550

970 674 8080 telephone
970 674 8088 facsimile
savagandsavage@earthlink.net



Transmittal

To: Ryan Hawkins
Company: Noble Energy, Inc.
Address: 804 Grand Avenue
City, State, Zip: Platteville, CO 80651

From: Edith Savage
Company: Savage and Savage, Inc.
Project: Betz PC G09-22D, Wetland Delineation
and Corps Concurrence
Phone: 970-674-8080
Fax: 970-674-8088
Date: August 6, 2011

Attached for your review is the Betz PC G09-22D wetland delineation and Corps concurrence request. Upon your approval I will submit this package to the Corps.

Savage and Savage *Environmental*

practical solutions for environmental issues

4610 Haystack Drive
Windsor, Colorado 80550

970 674 8080 telephone
970 674 8088 facsimile
savageandsavage@earthlink.net



September 7, 2011

Terry McKee
U.S. Army Corps of Engineers
9307 South Wadsworth Blvd.
Littleton, Colorado 80128-6901

**RE: Concurrence Request for Noble Energy Production, Inc.'s
Betz PC G09-22D Well Site, Weld County, Colorado
Corps File No. NWO-2010-1405-DEN**


Dear Mr. McKee:

Savage and Savage conducted a wetland delineation within the proposed Noble Energy, Betz PC G09-22D well site on August 9, 2011. This delineation was conducted in order to determine the presence and extent of wetlands within the proposed drill site. Hydrophytic vegetation was identified within three of the sample locations, however hydric soil and wetland hydrology were not identified within these sample sites (Sample Points 001, 003, 004). Hydrophytic vegetation, hydric soil, and wetland hydrology were identified within Sample Point 002. Wetlands are present along the south end of the field.

The proposed drill site is located approximately 0.13 miles west of Weld County Roads 46 and 43. The latitude of the project site is 40.321019 degrees north and longitude is 104.661109 degrees west. The site is located within the SE $\frac{1}{4}$ SE $\frac{1}{4}$ of Section 9, Township 4 North, Range 65 West of the 6th Prime Meridian, Weld County, Colorado.

The Betz PC G09-22D drill pad will be approximately 2.8 acres and will be located outside the wetland depicted on the wetland delineation aerial photograph. We request the Corps concur with our conclusion that there are no wetlands located within the proposed Betz PC G09-22D drill pad. If you have any questions or require further information about this site please contact me.

Sincerely,

A handwritten signature in black ink that reads "Edith Savage". The signature is written in a cursive, flowing style.

Edith Savage
Principal

attachment: Betz PC G09-22D Drill Site Wetland Delineation

c: Ryan Hawkins, Noble Energy, Inc.

**NOBLE ENERGY PRODUCTION, INC.
BETZ PC G09-22D DRILL SITE
WATERS OF THE UNITED STATES IDENTIFICATION
AND WETLAND DELINEATION
WELD COUNTY, COLORADO**



Prepared by: *Savage and Savage, Inc.*
4610 Haystack Drive
Windsor, CO 80550
970 674 8080

September 2011

TABLE OF CONTENTS

	<u>Page</u>
INTRODUCTION	1.
STUDY METHODS	1.
PROJECT DESCRIPTION	2.
SITE DESCRIPTION	2.
RESULTS/CONCLUSION	3.
LITERATURE CITED	4.
FIGURES	5.
APPENDIX	12.

FIGURES

1. Noble Energy Betz PC G09-22D Well General Location Map
2. Betz PC G09-22D Sample Point 1. Facing West
3. Betz PC G09-22D Sample Point 2. Facing West
4. Betz PC G09-22D Sample Point 3. Facing West
5. Betz PC G09-22D Sample Point 4. Facing West
6. Betz PC G09-22D Wetland Delineation (South Area)

APPENDIX

U.S. Army Corps of Engineers Great Plains – Interim Version Data Sheets

INTRODUCTION

Savage and Savage conducted a wetland delineation within the proposed Betz PC G09-22D drill site for Noble Energy Production, Inc. on August 9, 2011. The proposed drill site is located approximately 0.13 miles west of Weld County Roads 46 and 43, and is accessed by taking U.S. Highway 85 south from Greeley to La Salle (Main Street), South on Main Street to Todd Avenue (Weld County Road 50), east on Weld County Road 50 for approximately 2.25 miles to Weld County Road 43, south on Weld County Road 43 to the intersection of County Roads 43 and 46, west approximately 0.13 miles, then north onto an oil and gas access road. The latitude of the project site is 40.321019 degrees north and longitude is 104.661109 degrees west. The average elevation of the project site is 4710 feet. The site is located within the SE $\frac{1}{4}$ SE $\frac{1}{4}$ of Section 9, Township 4 North, Range 65 West of the 6th Prime Meridian, Weld County, Colorado (Figure 1).

STUDY METHODS

A wetland delineation was conducted in accordance with the requirements of the U.S. Army Corps of Engineers Wetlands Delineation Manual and Interim Supplement (USACE, 1987, 2008). To determine the areas subject to Corps jurisdiction, three criteria were evaluated: (1) evidence of a hydrologic regime reflecting saturation or periodic inundation by surface or ground water of sufficient duration and frequency, (2) soils which are considered hydric by classification or field characteristics indicating anaerobic conditions, and (3) a prevalence of vegetation typically adapted to areas of wetland hydrology and soils.

At four sample points within the proposed drill site the three wetland criteria were evaluated. Dominant individual plant species were identified, and their wetland indicator status was assessed (USFWS, 1988). Evidence of the hydrologic regime was collected and evaluated. A soil test pit was dug using a core auger to approximately 20 inches from the soil surface. Soil horizons were inspected and described using texture, soil color (Munsell, 1992), and moisture. Observations were recorded on the attached USACE

Great Plains – Interim Version approved data sheet (Figures 2 – 5 depict the sample points).

PROJECT DESCRIPTION

Proposed temporary disturbance will include construction of a drill pad that is approximately 2.8 acres. Permanent disturbance will include one fenced well head located on the drill pad remnant. The existing tank battery will be expanded for this project.

SITE DESCRIPTION

The significant topographic feature in the vicinity of the site is the Lower Latham Reservoir that is located approximately 1.25 miles northeast of the drill site and the Behrens Reservoir that is approximately 0.5 miles west of the drill site. The proposed disturbance area is a flat field that is used for grazing cattle.

The field is lower in elevation than the surrounding fields. Pivot irrigation is located to the south and upgradient of the project site. Some wetland vegetation is evidence of increased surface water runoff to this site.

One dominant soil map unit was identified in the area of the proposed project site. According to the Soil Survey of Weld County, Southern Part (1980), Loup-Boel loamy sands (0 to 3 percent slopes) are located within the area. This map unit is a nearly level map unit.

The Boel soil is deep and somewhat poorly drained and formed in stratified sandy alluvium. Typically the surface layer is grayish brown loamy sand about 14 inches thick. The water table is usually about 24 to 36 inches below the surface. Boel soil is not defined by the U.S. Army Corps of Engineers as hydric. On-site observation of soils within the site confirmed the presence of this soil map unit within the field.

Dominant plant species within the field are inland saltgrass (*Distichlis spicata*), three-square (*Scirpus Americanus*), Kentucky bluegrass (*Poa pratensis*), and meadow foxtail (*Hordeum jubatum*). Dominant plant species with the wet meadow wetland include meadow foxtail and three-square.

RESULTS/CONCLUSION


Savage and Savage conducted a wetland delineation at the proposed Noble Energy Production Betz PC G09-22D well site on August 9, 2011. This delineation was conducted in order to determine the presence and extent of wetlands within the proposed drill site. Hydrophytic vegetation was identified within three of the sample locations, however hydric soil and wetland hydrology were not identified within these sample sites (Sample Points 001, 003, 004). Hydrophytic vegetation, hydric soil, and wetland hydrology were identified within Sample Point 002. Wetlands are present along the south end of the field. (Figure 6).

LITERATURE CITED


- Killmorgen Instruments Corp. 1992. Munsell® Soil Color Charts. Newburg, NW.
- Munshower, Frank F. 1991. Perennial Grasses for Revegetation of Disturbed Lands in the Northern Great Plains and the Intermountain Region. Reclamation Research Unit, Montana State University, Bozeman, Montana.
- U.S. Army Corps of Engineers. 1987. Corps of Engineers Wetlands Delineation Manual. Technical Report Y-87-1. Department of the Army, Waterways Experiment Station, Vicksburg, Mississippi.
- U.S. Army Corps of Engineers. 2008. Interim Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Great Plains Region, ed. J.S. Wakeley, R.W. Lichvar, and C.V. Noble, ERDC/EL TR-08-12. Vicksburg, MS: U.S. Army Engineer Research and Development Center.
- U.S. Department of Agriculture Soil Conservation Service. 1980. Soil Survey of Weld County, Colorado, Southern Part.
- U.S. Fish and Wildlife Service. 1988. National List of Plant Species that Occur in Wetlands: Central Plains (Region 5). U.S. Department of Interior, Fish and Wildlife Service Research and Project, Biological Report 88(26.5), Washington, D.C.

FIGURES

Noble Energy Betz PC G09-22D Well General Location Map



Map created with TOPO! © 2006 National Geographic



TN MN
9 1/2°
09/06/11



Figure 2. Betz PC G09-22D Sample Point 1. Facing West



Figure 3. Betz PC G09-22D Sample Point 2. Facing West




Figure 4. Betz PC G09-22D Sample Point 3. Facing West



Figure 5. Betz PC G09-22D Sample Point 4. Facing West

Noble Energy Betz PC G 09-22 D Wetland Delineation (South Area)



Drill Pad Location

004

003

002

001

Wetlands

367 ft

603143

Data SIO, NOAA, U.S. Navy, NGA, GEBCO
© 2011 Google
Image © 2011 DigitalGlobe

© 2007
Google™

APPENDIX

SOIL

Sampling Point: 001

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²		
0-2"	7.5YR 2.5/1	95	NONE				CLAY LOAM	
2-11"	7.5YR 4/3	95	NONE				CLAYEY SAND	
11-20"	7.5YR 4/3	95	NONE				SANDY CLAY	

¹Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. ²Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)

<input type="checkbox"/> Histosol (A1) <input type="checkbox"/> Histic Epipedon (A2) <input type="checkbox"/> Black Histic (A3) <input type="checkbox"/> Hydrogen Sulfide (A4) <input type="checkbox"/> Stratified Layers (A5) (LRR F) <input type="checkbox"/> 1 cm Muck (A9) (LRR F, G, H) <input type="checkbox"/> Depleted Below Dark Surface (A11) <input type="checkbox"/> Thick Dark Surface (A12) <input type="checkbox"/> Sandy Mucky Mineral (S1) <input type="checkbox"/> 2.5 cm Mucky Peat or Peat (S2) (LRR G, H) <input type="checkbox"/> 5 cm Mucky Peat or Peat (S3) (LRR F)	<input type="checkbox"/> Sandy Gleyed Matrix (S4) <input type="checkbox"/> Sandy Redox (S5) <input type="checkbox"/> Stripped Matrix (S6) <input type="checkbox"/> Loamy Mucky Mineral (F1) <input type="checkbox"/> Loamy Gleyed Matrix (F2) <input type="checkbox"/> Depleted Matrix (F3) <input type="checkbox"/> Redox Dark Surface (F6) <input type="checkbox"/> Depleted Dark Surface (F7) <input type="checkbox"/> Redox Depressions (F8) <input type="checkbox"/> High Plains Depressions (F16) (MLRA 72 & 73 of LRR H)	Indicators for Problematic Hydric Soils³: <input type="checkbox"/> 1 cm Muck (A9) (LRR I, J) <input type="checkbox"/> Coast Prairie Redox (A16) (LRR F, G, H) <input type="checkbox"/> Dark Surface (S7) (LRR G) <input type="checkbox"/> High Plains Depressions (F16) (LRR H outside of MLRA 72 & 73) <input type="checkbox"/> Reduced Vertic (F18) <input type="checkbox"/> Red Parent Material (TF2) <input type="checkbox"/> Other (Explain in Remarks) ³ Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.
--	--	--

Restrictive Layer (if present):
 Type: _____
 Depth (inches): _____

Hydric Soil Present? Yes _____ No

Remarks:

HYDROLOGY

Wetland Hydrology Indicators:

<u>Primary Indicators (minimum of one required; check all that apply)</u>		<u>Secondary Indicators (minimum of two required)</u>
<input type="checkbox"/> Surface Water (A1) <input type="checkbox"/> High Water Table (A2) <input type="checkbox"/> Saturation (A3) <input type="checkbox"/> Water Marks (B1) <input type="checkbox"/> Sediment Deposits (B2) <input type="checkbox"/> Drift Deposits (B3) <input type="checkbox"/> Algal Mat or Crust (B4) <input type="checkbox"/> Iron Deposits (B5) <input type="checkbox"/> Inundation Visible on Aerial Imagery (B7) <input type="checkbox"/> Water-Stained Leaves (B9)	<input type="checkbox"/> Salt Crust (B11) <input type="checkbox"/> Aquatic Invertebrates (B13) <input type="checkbox"/> Hydrogen Sulfide Odor (C1) <input type="checkbox"/> Dry-Season Water Table (C2) <input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3) (where not tilled) <input type="checkbox"/> Presence of Reduced Iron (C4) <input type="checkbox"/> Thin Muck Surface (C7) <input type="checkbox"/> Other (Explain in Remarks)	<input type="checkbox"/> Surface Soil Cracks (B6) <input type="checkbox"/> Sparsely Vegetated Concave Surface (B8) <input type="checkbox"/> Drainage Patterns (B10) <input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3) (where tilled) <input type="checkbox"/> Crayfish Burrows (C8) <input type="checkbox"/> Saturation Visible on Aerial Imagery (C9) <input checked="" type="checkbox"/> Geomorphic Position (D2) <input type="checkbox"/> FAC-Neutral Test (D5) <input type="checkbox"/> Frost-Heave Hummocks (D7) (LRR F)

Field Observations:

Surface Water Present? Yes _____ No <input checked="" type="checkbox"/>	Depth (inches): _____	Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>
Water Table Present? Yes _____ No <input checked="" type="checkbox"/>	Depth (inches): _____	
Saturation Present? (includes capillary fringe) Yes _____ No <input checked="" type="checkbox"/>	Depth (inches): _____	

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

WETLAND DETERMINATION DATA FORM – Great Plains Region

Project/Site: BETZ PCG09-22D City/County: WELD Sampling Date: AUG 9, 2011
 Applicant/Owner: NOBLE ENERGY State: CO Sampling Point: 002
 Investigator(s): MS SAVAGE / EA SAVAGE Section, Township, Range: SEC 9, TAN, R6SW
 Landform (hillslope, terrace, etc.): FUT FIELD Local relief (concave, convex, none): (none) Slope (%): <1
 Subregion (LRR): _____ Lat: _____ Long: _____ Datum: _____
 Soil Map Unit Name: _____ NWI classification: _____

Are climatic / hydrologic conditions on the site typical for this time of year? Yes X No _____ (If no, explain in Remarks.)
 Are Vegetation _____, Soil _____, or Hydrology _____ significantly disturbed? Are "Normal Circumstances" present? Yes X No _____
 Are Vegetation _____, Soil _____, or Hydrology _____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present? Yes <u>X</u> No _____ Hydric Soil Present? Yes <u>X</u> No _____ Wetland Hydrology Present? Yes <u>X</u> No _____	Is the Sampled Area within a Wetland? Yes <u>X</u> No _____
Remarks: <u>200' E OF TANK FARM FENCE, 75' SOUTH OF TANK FARM N BOUNDARY</u>	

VEGETATION – Use scientific names of plants.

Tree Stratum (Plot size: <u>N/A</u>)	Absolute % Cover	Dominant Species?	Indicator Status	Dominance Test worksheet:
1. _____				Number of Dominant Species That Are OBL, FACW, or FAC (excluding FAC-): <u>2</u> (A) Total Number of Dominant Species Across All Strata: <u>2</u> (B) Percent of Dominant Species That Are OBL, FACW, or FAC: <u>100%</u> (A/B)
2. _____				
3. _____				
4. _____				
_____ = Total Cover				Prevalence Index worksheet: Total % Cover of: _____ Multiply by: OBL species <u>30</u> x 1 = <u>30</u> FACW species <u>45</u> x 2 = <u>90</u> FAC species <u>3</u> x 3 = <u>9</u> FACU species <u>2</u> x 4 = <u>8</u> UPL species <u>0</u> x 5 = <u>0</u> Column Totals: <u>80</u> (A) <u>137</u> (B) Prevalence Index = B/A = <u>1.7</u>
Sapling/Shrub Stratum (Plot size: <u>N/A</u>)				
1. _____				
2. _____				
3. _____				
4. _____				
5. _____				
_____ = Total Cover				
Herb Stratum (Plot size: <u>10'x10'</u>)				
1. <u>Scirpus americanus</u>	<u>30</u>	<u>Y</u>	<u>OBL</u>	
2. <u>Hordeum jubatum</u>	<u>45</u>	<u>Y</u>	<u>FACW</u>	
3. <u>Bromus inermis</u>	<u>2</u>	<u>N</u>	<u>FACU</u>	
4. <u>Cirsium arvense</u>	<u>3</u>	<u>N</u>	<u>FAC</u>	
5. _____				
6. _____				
7. _____				
8. _____				
9. _____				
10. _____				
<u>80</u> = Total Cover				
Woody Vine Stratum (Plot size: <u>N/A</u>)				
1. _____				
2. _____				
_____ = Total Cover				
% Bare Ground in Herb Stratum <u>10%</u>				
Hydrophytic Vegetation Present? Yes <u>X</u> No _____				
Remarks: _____				

SOIL

Sampling Point: 002

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²		
0-3"	7.5YR 2.5/1	95	NONE				CLAY LOAM	
3-21"	7.5YR 3/2	95	NONE				SANDY LOAM	

¹Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. ²Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)

<input type="checkbox"/> Histosol (A1)	<input type="checkbox"/> Sandy Gleyed Matrix (S4)	<input type="checkbox"/> 1 cm Muck (A9) (LRR I, J)
<input type="checkbox"/> Histic Epipedon (A2)	<input type="checkbox"/> Sandy Redox (S5)	<input type="checkbox"/> Coast Prairie Redox (A16) (LRR F, G, H)
<input type="checkbox"/> Black Histic (A3)	<input type="checkbox"/> Stripped Matrix (S6)	<input type="checkbox"/> Dark Surface (S7) (LRR G)
<input type="checkbox"/> Hydrogen Sulfide (A4)	<input type="checkbox"/> Loamy Mucky Mineral (F1)	<input type="checkbox"/> High Plains Depressions (F16)
<input type="checkbox"/> Stratified Layers (A5) (LRR F)	<input type="checkbox"/> Loamy Gleyed Matrix (F2)	<input type="checkbox"/> (LRR H outside of MLRA 72 & 73)
<input type="checkbox"/> 1 cm Muck (A9) (LRR F, G, H)	<input type="checkbox"/> Depleted Matrix (F3)	<input type="checkbox"/> Reduced Vertic (F18)
<input type="checkbox"/> Depleted Below Dark Surface (A11)	<input checked="" type="checkbox"/> Redox Dark Surface (F6)	<input type="checkbox"/> Red Parent Material (TF2)
<input type="checkbox"/> Thick Dark Surface (A12)	<input type="checkbox"/> Depleted Dark Surface (F7)	<input type="checkbox"/> Other (Explain in Remarks)
<input type="checkbox"/> Sandy Mucky Mineral (S1)	<input type="checkbox"/> Redox Depressions (F8)	³ Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.
<input type="checkbox"/> 2.5 cm Mucky Peat or Peat (S2) (LRR G, H)	<input type="checkbox"/> High Plains Depressions (F16)	
<input type="checkbox"/> 5 cm Mucky Peat or Peat (S3) (LRR F)	<input type="checkbox"/> (MLRA 72 & 73 of LRR H)	

Restrictive Layer (if present):
 Type: _____
 Depth (inches): _____

Hydric Soil Present? Yes No

Remarks:

HYDROLOGY

Wetland Hydrology Indicators:

Primary Indicators (minimum of one required; check all that apply)	Secondary Indicators (minimum of two required)
<input type="checkbox"/> Surface Water (A1)	<input type="checkbox"/> Surface Soil Cracks (B6)
<input type="checkbox"/> High Water Table (A2)	<input type="checkbox"/> Sparsely Vegetated Concave Surface (B8)
<input type="checkbox"/> Saturation (A3)	<input type="checkbox"/> Drainage Patterns (B10)
<input type="checkbox"/> Water Marks (B1)	<input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3)
<input type="checkbox"/> Sediment Deposits (B2)	<input type="checkbox"/> (where tilled)
<input type="checkbox"/> Drift Deposits (B3)	<input type="checkbox"/> Crayfish Burrows (C8)
<input type="checkbox"/> Algal Mat or Crust (B4)	<input type="checkbox"/> Saturation Visible on Aerial Imagery (C9)
<input type="checkbox"/> Iron Deposits (B5)	<input checked="" type="checkbox"/> Geomorphic Position (D2)
<input type="checkbox"/> Inundation Visible on Aerial Imagery (B7)	<input checked="" type="checkbox"/> FAC-Neutral Test (D5)
<input type="checkbox"/> Water-Stained Leaves (B9)	<input type="checkbox"/> Frost-Heave Hummocks (D7) (LRR F)
<input type="checkbox"/> Salt Crust (B11)	
<input type="checkbox"/> Aquatic Invertebrates (B13)	
<input type="checkbox"/> Hydrogen Sulfide Odor (C1)	
<input type="checkbox"/> Dry-Season Water Table (C2)	
<input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3) (where not tilled)	
<input type="checkbox"/> Presence of Reduced Iron (C4)	
<input type="checkbox"/> Thin Muck Surface (C7)	
<input type="checkbox"/> Other (Explain in Remarks)	

Field Observations:

Surface Water Present? Yes No Depth (inches): _____

Water Table Present? Yes No Depth (inches): _____

Saturation Present? (includes capillary fringe) Yes No Depth (inches): _____

Wetland Hydrology Present? Yes No

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

WETLAND DETERMINATION DATA FORM – Great Plains Region

Project/Site: BETZ PC G09-22D City/County: WBD Sampling Date: AUG 9, 2011
 Applicant/Owner: NOBLE ENERGY State: CO Sampling Point: 003
 Investigator(s): MS SAVAGE / IEA SAVAGE Section, Township, Range: S19, T4N, R65W
 Landform (hillslope, terrace, etc.): FLAT FIELD Local relief (concave, convex, none): (none) Slope (%): <1
 Subregion (LRR): _____ Lat: _____ Long: _____ Datum: _____
 Soil Map Unit Name: _____ NWI classification: _____

Are climatic / hydrologic conditions on the site typical for this time of year? Yes No _____ (If no, explain in Remarks.)
 Are Vegetation _____, Soil _____, or Hydrology _____ significantly disturbed? Are "Normal Circumstances" present? Yes No _____
 Are Vegetation _____, Soil _____, or Hydrology _____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present? Yes <input checked="" type="checkbox"/> No _____ Hydric Soil Present? Yes _____ No <input checked="" type="checkbox"/> Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>	Is the Sampled Area within a Wetland? Yes _____ No <input checked="" type="checkbox"/>
Remarks: <u>50' WEST OF PROPOSED DRILL SITE FENCE (SW CORNER)</u> <u>PROPOSED DRILL SITE 165' WIDE FROM ROAD</u>	

VEGETATION – Use scientific names of plants.

Tree Stratum (Plot size: _____)	Absolute % Cover	Dominant Species?	Indicator Status	Dominance Test worksheet:														
1. _____	_____	_____	_____	Number of Dominant Species That Are OBL, FACW, or FAC (excluding FAC-): <u>3</u> (A) Total Number of Dominant Species Across All Strata: <u>3</u> (B) Percent of Dominant Species That Are OBL, FACW, or FAC: <u>100%</u> (A/B)														
2. _____	_____	_____	_____															
3. _____	_____	_____	_____															
4. _____	_____	_____	_____															
_____ = Total Cover				Prevalence Index worksheet: <table style="width:100%; border-collapse: collapse;"> <tr> <td style="width:50%;">Total % Cover of:</td> <td style="width:50%;">Multiply by:</td> </tr> <tr> <td>OBL species <u>10</u></td> <td>x 1 = <u>10</u></td> </tr> <tr> <td>FACW species <u>10</u></td> <td>x 2 = <u>20</u></td> </tr> <tr> <td>FAC species <u>30</u></td> <td>x 3 = <u>90</u></td> </tr> <tr> <td>FACU species <u>5</u></td> <td>x 4 = <u>20</u></td> </tr> <tr> <td>UPL species _____</td> <td>x 5 = _____</td> </tr> <tr> <td>Column Totals: <u>55</u> (A)</td> <td><u>140</u> (B)</td> </tr> </table> Prevalence Index = B/A = <u>2.5</u>	Total % Cover of:	Multiply by:	OBL species <u>10</u>	x 1 = <u>10</u>	FACW species <u>10</u>	x 2 = <u>20</u>	FAC species <u>30</u>	x 3 = <u>90</u>	FACU species <u>5</u>	x 4 = <u>20</u>	UPL species _____	x 5 = _____	Column Totals: <u>55</u> (A)	<u>140</u> (B)
Total % Cover of:	Multiply by:																	
OBL species <u>10</u>	x 1 = <u>10</u>																	
FACW species <u>10</u>	x 2 = <u>20</u>																	
FAC species <u>30</u>	x 3 = <u>90</u>																	
FACU species <u>5</u>	x 4 = <u>20</u>																	
UPL species _____	x 5 = _____																	
Column Totals: <u>55</u> (A)	<u>140</u> (B)																	
Sapling/Shrub Stratum (Plot size: _____) 1. _____ 2. _____ 3. _____ 4. _____ 5. _____ _____ = Total Cover																		
Herb Stratum (Plot size: <u>10'x10'</u>) 1. <u>Dactylis spicata</u> <u>30</u> <u>Y</u> <u>NT(FAC)</u> 2. <u>Scirpus americanus</u> <u>10</u> <u>Y</u> <u>OBL</u> 3. <u>Hordeum jubatum</u> <u>10</u> <u>Y</u> <u>FACW</u> 4. <u>Poa pratensis</u> <u>5</u> <u>N</u> <u>FACU</u> 5. _____ 6. _____ 7. _____ 8. _____ 9. _____ 10. _____ _____ = Total Cover																		
Woody Vine Stratum (Plot size: _____) 1. _____ 2. _____ _____ = Total Cover																		
% Bare Ground in Herb Stratum <u>15</u> _____ = Total Cover																		
Remarks: _____																		

Hydrophytic Vegetation Indicators:
 ___ Dominance Test is >50%
 ___ Prevalence Index is ≤3.0¹
 ___ Morphological Adaptations¹ (Provide supporting data in Remarks or on a separate sheet)
 ___ Problematic Hydrophytic Vegetation¹ (Explain)

¹Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.

Hydrophytic Vegetation Present? Yes No _____

SOIL

Sampling Point: 003

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)

Depth (inches)	Matrix		Redox Features				Texture	Remarks
	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²		
0-4"	7.5YR 2-5/1	95	NONE				CLAY LOAM	
4-18"	7.5YR 4/3		NONE				CLAYEY SAND	
18-24"	7.5YR 4/3		NONE				SANDY CLAY	

¹Type: C=Concentration, D=Depletion, RM=Reduced Matrix, CS=Covered or Coated Sand Grains. ²Location: PL=Pore Lining, M=Matrix.

Hydric Soil Indicators: (Applicable to all LRRs, unless otherwise noted.)

<input type="checkbox"/> Histosol (A1)	<input type="checkbox"/> Sandy Gleyed Matrix (S4)	<input type="checkbox"/> 1 cm Muck (A9) (LRR I, J)
<input type="checkbox"/> Histic Epipedon (A2)	<input type="checkbox"/> Sandy Redox (S5)	<input type="checkbox"/> Coast Prairie Redox (A16) (LRR F, G, H)
<input type="checkbox"/> Black Histic (A3)	<input type="checkbox"/> Stripped Matrix (S6)	<input type="checkbox"/> Dark Surface (S7) (LRR G)
<input type="checkbox"/> Hydrogen Sulfide (A4)	<input type="checkbox"/> Loamy Mucky Mineral (F1)	<input type="checkbox"/> High Plains Depressions (F16)
<input type="checkbox"/> Stratified Layers (A5) (LRR F)	<input type="checkbox"/> Loamy Gleyed Matrix (F2)	<input type="checkbox"/> (LRR H outside of MLRA 72 & 73)
<input type="checkbox"/> 1 cm Muck (A9) (LRR F, G, H)	<input type="checkbox"/> Depleted Matrix (F3)	<input type="checkbox"/> Reduced Vertic (F18)
<input type="checkbox"/> Depleted Below Dark Surface (A11)	<input checked="" type="checkbox"/> Redox Dark Surface (F6)	<input type="checkbox"/> Red Parent Material (TF2)
<input type="checkbox"/> Thick Dark Surface (A12)	<input type="checkbox"/> Depleted Dark Surface (F7)	<input type="checkbox"/> Other (Explain in Remarks)
<input type="checkbox"/> Sandy Mucky Mineral (S1)	<input type="checkbox"/> Redox Depressions (F8)	³ Indicators of hydrophytic vegetation and wetland hydrology must be present, unless disturbed or problematic.
<input type="checkbox"/> 2.5 cm Mucky Peat or Peat (S2) (LRR G, H)	<input type="checkbox"/> High Plains Depressions (F16) (MLRA 72 & 73 of LRR H)	
<input type="checkbox"/> 5 cm Mucky Peat or Peat (S3) (LRR F)		

Restrictive Layer (if present):
 Type: _____
 Depth (inches): _____

Hydric Soil Present? Yes _____ No

Remarks:

HYDROLOGY

Wetland Hydrology Indicators:

<u>Primary Indicators (minimum of one required; check all that apply)</u>		<u>Secondary Indicators (minimum of two required)</u>
<input type="checkbox"/> Surface Water (A1)	<input type="checkbox"/> Salt Crust (B11)	<input type="checkbox"/> Surface Soil Cracks (B6)
<input type="checkbox"/> High Water Table (A2)	<input type="checkbox"/> Aquatic Invertebrates (B13)	<input type="checkbox"/> Sparsely Vegetated Concave Surface (B8)
<input type="checkbox"/> Saturation (A3)	<input type="checkbox"/> Hydrogen Sulfide Odor (C1)	<input type="checkbox"/> Drainage Patterns (B10)
<input type="checkbox"/> Water Marks (B1)	<input type="checkbox"/> Dry-Season Water Table (C2)	<input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3)
<input type="checkbox"/> Sediment Deposits (B2)	<input type="checkbox"/> Oxidized Rhizospheres on Living Roots (C3) (where not tilled)	<input type="checkbox"/> Crayfish Burrows (C8)
<input type="checkbox"/> Drift Deposits (B3)	<input type="checkbox"/> Presence of Reduced Iron (C4)	<input type="checkbox"/> Saturation Visible on Aerial Imagery (C9)
<input type="checkbox"/> Algal Mat or Crust (B4)	<input type="checkbox"/> Thin Muck Surface (C7)	<input checked="" type="checkbox"/> Geomorphic Position (D2)
<input type="checkbox"/> Iron Deposits (B5)	<input type="checkbox"/> Other (Explain in Remarks)	<input type="checkbox"/> FAC-Neutral Test (D5)
<input type="checkbox"/> Inundation Visible on Aerial Imagery (B7)		<input type="checkbox"/> Frost-Heave Hummocks (D7) (LRR F)
<input type="checkbox"/> Water-Stained Leaves (B9)		

Field Observations:

Surface Water Present? Yes _____ No _____	Depth (inches): _____	Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>
Water Table Present? Yes _____ No _____	Depth (inches): _____	
Saturation Present? Yes _____ No _____	Depth (inches): _____	

(includes capillary fringe)

Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:

Remarks:

WETLAND DETERMINATION DATA FORM – Great Plains Region

Project/Site: BETZ PC 609-22D City/County: WELD Sampling Date: AVG 9, 2011
 Applicant/Owner: NOBLE ENERGY State: CO Sampling Point: 004
 Investigator(s): MS SAVAGE / EA SAVAGE Section, Township, Range: 5E, 9, TAN, R65W
 Landform (hillslope, terrace, etc.): FLAT FIELD Local relief (concave, convex, none): none Slope (%): 1
 Subregion (LRR): _____ Lat: _____ Long: _____ Datum: _____
 Soil Map Unit Name: _____ NWI classification: _____

Are climatic / hydrologic conditions on the site typical for this time of year? Yes No _____ (If no, explain in Remarks.)
 Are Vegetation _____, Soil _____, or Hydrology _____ significantly disturbed? Are "Normal Circumstances" present? Yes No _____
 Are Vegetation _____, Soil _____, or Hydrology _____ naturally problematic? (If needed, explain any answers in Remarks.)

SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.

Hydrophytic Vegetation Present? Yes _____ No <input checked="" type="checkbox"/> Hydric Soil Present? Yes _____ No <input checked="" type="checkbox"/> Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>	Is the Sampled Area within a Wetland? Yes _____ No <input checked="" type="checkbox"/>
Remarks: <u>300' SOUTH OF PASTURE FENCE, 50' WEST OF PROPOSED DRILL PAD BOUNDARY FENCE; ~ 100' WEST OF EXISTING DRILL HEAD (290' SOUTH OF PASTURE FENCE) PROPOSED DRILL PAD 420' (N-S),</u>	

VEGETATION – Use scientific names of plants.

Tree Stratum (Plot size: <u>N/A</u>)	Absolute % Cover	Dominant Species?	Indicator Status	Dominance Test worksheet:
1. _____	_____	_____	_____	Number of Dominant Species That Are OBL, FACW, or FAC (excluding FAC-): <u>1</u> (A) Total Number of Dominant Species Across All Strata: <u>1</u> (B) Percent of Dominant Species That Are OBL, FACW, or FAC: <u>100</u> (AB)
2. _____	_____	_____	_____	
3. _____	_____	_____	_____	
4. _____	_____	_____	_____	
_____ = Total Cover				Prevalence Index worksheet: Total % Cover of: _____ Multiply by: _____ OBL species <u>0</u> x 1 = _____ FACW species <u>1</u> x 2 = <u>2</u> FAC species <u>45</u> x 3 = <u>135</u> FACU species <u>7</u> x 4 = <u>28</u> UPL species <u>0</u> x 5 = _____ Column Totals: <u>53</u> (A) _____ (B) Prevalence Index = B/A = <u>3.1</u>
Sapling/Shrub Stratum (Plot size: <u>N/A</u>)				
1. _____	_____	_____	_____	
2. _____	_____	_____	_____	
3. _____	_____	_____	_____	
Herb Stratum (Plot size: <u>10'X10'</u>)				
1. <u>Distichlis spicata</u>	<u>45</u>	<u>Y</u>	<u>N(FAC)</u>	
2. <u>Poa pratensis</u>	<u>2</u>	<u>N</u>	<u>FACU</u>	
3. <u>Hierdenm jubatum</u>	<u>1</u>	<u>N</u>	<u>FACW</u>	
4. <u>Dactylis glomerata</u>	<u>5</u>	<u>N</u>	<u>FACU</u>	
5. _____	_____	_____	_____	
6. _____	_____	_____	_____	
7. _____	_____	_____	_____	
8. _____	_____	_____	_____	
9. _____	_____	_____	_____	
10. _____	_____	_____	_____	
<u>53</u> = Total Cover				
Woody Vine Stratum (Plot size: <u>N/A</u>)				
1. _____	_____	_____	_____	
2. _____	_____	_____	_____	
% Bare Ground in Herb Stratum <u>15%</u> _____ = Total Cover				
Remarks: _____				
Hydrophytic Vegetation Present? Yes <input checked="" type="checkbox"/> No _____				

