

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400449868

Date Received:

07/18/2013

SUNDRY NOTICE

Submit a signed original. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full in Comments or provide as an attachment. Identify Well by API Number; identify Oil and Gas Location by Location ID Number; identify other Facility by Facility ID Number.

OGCC Operator Number:	3380	Contact Name	Mindy Paulek
Name of Operator:	APACHE CORPORATION		Phone: (970) 426-7020
Address:	2000 POST OAK BLVD #100		Fax: ()
City:	HOUSTON	State:	TX
Zip:	77056-4400	Email:	mindy.paulek@urs.com

Complete the Attachment Checklist

OP OGCC

API Number :	05-	087	06484	00	OGCC Facility ID Number:	226014
Well/Facility Name:	CLARENCE E. BRUCE				Well/Facility Number:	1
Location	QtrQtr:	NWNE	Section:	14	Township:	5N
					Range:	56W
					Meridian:	6
County:	MORGAN		Field Name:	WILDCAT		
Federal, Indian or State Lease Number:						

Survey Plat		
Directional Survey		
Srvc Eqpmt Diagram		
Technical Info Page		
Other		

CHANGE OF LOCATION OR AS BUILT GPS REPORT

☐ Change of Location * ☐ As-Built GPS Location Report ☐ As-Built GPS Location Report with Survey

* Well location change requires new plat. A substantive surface location change may require new Form 2A.

SURFACE LOCATION GPS DATA Data must be provided for Change of Surface Location and As Built Reports.

Latitude _____ PDOP Reading _____ Date of Measurement _____
Longitude _____ GPS Instrument Operator's Name _____

LOCATION CHANGE (all measurements in Feet)

Well will be: (Vertical, Directional, Horizontal)

Change of **Surface** Footage **From** Exterior Section Lines:

Change of **Surface** Footage To Exterior Section Lines:

Current Surface Location From	QtrQtr	NWNE	Sec	14
---	--------	------	-----	----

New **Surface** Location To QtrQtr Sec

Change of **Top of Productive Zone** Footage From Exterior Section Lines:

Change of **Top of Productive Zone** Footage To Exterior Section Lines:

Current **Top of Productive Zone** Location From Sec

New **Top of Productive Zone** Location To Sec

Change of **Bottomhole** Footage **From** Exterior Section Lines:

Change of **Bottomhole** Footage To Exterior Section Lines:

Current **Bottomhole** Location Sec Twp

New **Bottomhole** Location Sec Twp

Is location in High Density Area?

Distance, in feet, to nearest building _____, public road: _____, above ground utility: _____, railroad: _____,

property line: _____, lease line: _____, well in same formation: _____

Ground Elevation feet Surface owner consultation date

FNL/FSL		FEL/FWL		
660	FNL	1980	FEL	
Twp	5N	Range	56W	Meridian
Twp		Range		Meridian
				**
Twp		Range		
Twp		Range		
				**
Range		** attach deviated drilling plan		
Range				

** attach deviated drilling plan

CHANGE OR ADD OBJECTIVE FORMATION AND/OR SPACING UNIT

<u>Objective Formation</u>	<u>Formation Code</u>	<u>Spacing Order Number</u>	<u>Unit Acreage</u>	<u>Unit Configuration</u>

OTHER CHANGES

☐ **REMOVE FROM SURFACE BOND** Signed surface use agreement is a required attachment

☐ **CHANGE OF WELL, FACILITY OR OIL & GAS LOCATION NAME OR NUMBER**

From: Name CLARENCE E. BRUCE Number 1 Effective Date: _____

To: Name _____ Number _____

☐ **ABANDON PERMIT: Permit can only be abandoned if the permitted operation has NOT been conducted. Field inspection will be conducted to verify site status.**

☐ WELL: Abandon Application for Permit-to-Drill (Form2) – Well API Number _____ has not been drilled.

☐ PIT: Abandon Earthen Pit Permit (Form 15) – COGCC Pit Facility ID Number _____ has not been constructed (Permitted and constructed pit requires closure per Rule 905)

☐ CENTRALIZED E&P WASTE MANAGEMENT FACILITY: Abandon Centralized E&P Waste Management Facility Permit (Form 28) – Facility ID Number _____ has not been constructed (Constructed facility requires closure per Rule 908)

OIL & GAS LOCATION ID Number: _____

☐ Abandon Oil & Gas Location Assessment (Form 2A) – Location has not been constructed and site will not be used in the future.

☐ Keep Oil & Gas Location Assessment (Form 2A) active until expiration date. This site will be used in the future.

Surface disturbance from Oil and Gas Operations must be reclaimed per Rule 1003 and Rule 1004.

☐ **REQUEST FOR CONFIDENTIAL STATUS**

☐ **DIGITAL WELL LOG UPLOAD**

☐ **DOCUMENTS SUBMITTED** Purpose of Submission: _____

RECLAMATION**INTERIM RECLAMATION**

☐ Interim Reclamation will commence approximately _____

Per Rule 1003.e.(3) operator shall submit Sundry Notice reporting interim reclamation is complete and site is ready for inspection when vegetation reaches 80% coverage.

☐ Interim reclamation complete, site ready for inspection.

Per Rule 1003.e(3) describe interim reclamation procedure in Comments below or provide as an attachment and attach required location photographs.

Field inspection will be conducted to document Rule 1003.e. compliance

FINAL RECLAMATION

☐ Final Reclamation will commence approximately _____

Per Rule 1004.c.(4) operator shall submit Sundry Notice reporting final reclamation is complete and site is ready for inspection when vegetation reaches 80% coverage.

☒ Final reclamation complete, site ready for inspection. Per Rule 1004.c(4) describe final reclamation procedure in Comments below or provide as an attachment.

Field inspection will be conducted to document Rule 1004.c. compliance

Comments:

The well was plugged on May 27, 1958 and reclaimed thereafter. Specific reclamation procedures are unknown by current Apache personnel. However, the site is currently vegetated and does not appear to pose an erosional hazard. Aerial orthophotos as far back as 1989 show evidence that the site was re-vegetated with a total percent plant cover matching that of the surrounding area. The site was viewed at a distance from the county road and appears to generally blend into the natural contours of the hillslope. There does appear to be a small area that is not fully revegetated and may be the result of a small cut into the hillslope, however it is minimal in size and more damage may be done to the larger area in an attempt to blend and reseed this small portion. The land owner would prefer to leave the site as is and has signed a Surface Release (See Attachment).

ENGINEERING AND ENVIRONMENTAL WORK☐ NOTICE OF CONTINUED TEMPORARILY ABANDONED STATUS

Indicate why the well is temporarily abandoned and describe future plans for utilization in the COMMENTS box below or provide as an attachment, as required by Rule 319.b.(3).

Date well temporarily abandoned _____ Has Production Equipment been removed from site? _____

Mechanical Integrity Test (MIT) required if shut in longer than 2 years. Date of last MIT _____

☐ SPUD DATE: _____**TECHNICAL ENGINEERING AND ENVIRONMENTAL WORK**

Details of work must be described in full in the COMMENTS below or provided as an attachment.

☐ NOTICE OF INTENT Approximate Start Date _____

☒ REPORT OF WORK DONE Date Work Completed 07/08/2013

- | | | |
|--|---|--|
| <input type="checkbox"/> Intent to Recomplete (Form 2 also required) | <input type="checkbox"/> Request to Vent or Flare | <input type="checkbox"/> E&P Waste Management Plan |
| <input type="checkbox"/> Change Drilling Plan | <input type="checkbox"/> Repair Well | <input type="checkbox"/> Beneficial Reuse of E&P Waste |
| <input type="checkbox"/> Gross Interval Change | <input type="checkbox"/> Rule 502 variance requested. Must provide detailed info regarding request. | |
| <input type="checkbox"/> Other _____ | <input type="checkbox"/> Status Update/Change of Remediation Plans for Spills and Releases | |

COMMENTS:

The well was plugged on May 27, 1958 and reclaimed thereafter. Specific reclamation procedures are unknown by current Apache personnel. However, the site is currently vegetated and does not appear to pose an erosional hazard. Aerial orthophotos as far back as 1989 show evidence that the site was re-vegetated with a total percent plant cover matching that of the surrounding area. The site was viewed at a distance from the county road and appears to generally blend into the natural contours of the hillslope. There does appear to be a small area that is not fully revegetated and may be the result of a small cut into the hillslope, however it is minimal in size and more damage may be done to the larger area in an attempt to blend and reseed this small portion. The land owner would prefer to leave the site as is and has signed a Surface Release (See Attachment).

CASING AND CEMENTING CHANGES

Casing Type	Size	Of	/	Hole	Size	Of	/	Casing	Wt/Ft	Csg/LinTop	Setting Depth	Sacks of Cement	Cement Bottom	Cement Top

H2S REPORTING

Data Fields in this section are intended to document Sample and Location Data associated with the collection of a Gas Sample that is submitted for Laboratory Analysis.

Gas Analysis Report must be attached.

H2S Concentration: _____ in ppm (parts per million) Date of Measurement or Sample Collection _____

Description of Sample Point:

Absolute Open Flow Potential _____ in CFPD (cubic feet per day)

Description of Release Potential and Duration (If flow is not open to the atmosphere, identify the duration in which the container or pipeline would likely be opened for servicing operations.):

Distance to nearest occupied residence, school, church, park, school bus stop, place of business, or other areas where the public could reasonably be expected to frequent: _____

Distance to nearest Federal, State, County, or municipal road or highway owned and principally maintained for public use: _____

COMMENTS:

Best Management Practices

No BMP/COA Type

Description

--	--	--

Operator Comments:

The well was plugged on May 27, 1958 and reclaimed thereafter. Specific reclamation procedures are unknown by current Apache personnel. However, the site is currently vegetated and does not appear to pose an erosional hazard. Aerial orthophotos as far back as 1989 show evidence that the site was re-vegetated with a total percent plant cover matching that of the surrounding area. The site was viewed at a distance from the county road and appears to generally blend into the natural contours of the hillslope. There does appear to be a small area that is not fully revegetated and may be the result of a small cut into the hillslope, however it is minimal in size and more damage may be done to the larger area in an attempt to blend and reseed this small portion. The land owner would prefer to leave the site as is and has signed a Surface Release (See Attachment).

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Mindy Paulek
Title: Senior Biologist Email: mindy.paulek@urs.com Date: 7/18/2013

Based on the information provided herein, this Sundry Notice (Form 4) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: ASH, MARGARET Date: 11/11/2013

CONDITIONS OF APPROVAL, IF ANY:**COA Type****Description**

--	--

General Comments**User Group****Comment****Comment Date**

Permit	Well completion or recompletion report doc. # 482082 dated 7/11/1958	3/6/2013 5:49:11 AM
--------	--	---------------------

Total: 1 comment(s)

Attachment Check List**Att Doc Num****Name**

400449868	FORM 4 SUBMITTED
400449994	WAIVERS

Total Attach: 2 Files