

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

12/17/2013

Document Number:

668601826

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|-------------|--------|-----------------|--|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection |
| | 208598 | 381217 | QUINT, CRAIG | <input type="checkbox"/> 2A Doc Num: _____ |

Operator Information:

OGCC Operator Number: _____

Name of Operator: KUENZLER & FLORA RESERVE COMPANYAddress: 3310 W AQUEDUCT AVECity: LITTLETON State: CO Zip: 80123

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|--------------------------|---------|
| Kuenzler, Zane | 720-261-2019 | zanekuenzler@kfrcorp.com | |

Compliance Summary:QtrQtr: NENE Sec: 36 Twp: 12S Range: 46W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 12/21/2012 | 668600123 | PR | PR | Satisfactory | P | | No |
| 12/04/1997 | 500140980 | SR | DA | | P | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|-------------------------------------|
| 208598 | WELL | PR | 09/04/2012 | DA | 017-07533 | RED LADY 1-36 | PR | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|-----------------------------|-------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: <u>1</u> | Wells: <u>1</u> | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Lease Road:**

| Type | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
|--------|-----------------------------|--------------------------------------|----------------------------------|------|
| Access | Satisfactory | DIRT ROAD THROUGH PASTURE WITH RUTS. | ROAD COULD USE SOME MAINTENANCE. | |

| Signs/Marker: | | | | |
|----------------------|-----------------------------|---------------------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | Satisfactory | STICKERS | | |
| WELLHEAD | Satisfactory | LEASE SIGN BY WELL | | |
| BATTERY | Satisfactory | LEASE SIGN BY TANKS | | |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|-----------------------------|---|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| TANK BATTERY | Satisfactory | WIRE PANELS AROUND ALL BATTERY EQUIPMENT | | |
| WELLHEAD | Satisfactory | WIRE PANELS AROUND ALL WELLHEAD EQUIPMENT | | |

| Equipment: | | | | | |
|---------------------|---|-----------------------------|--|-------------------|---------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Ancillary equipment | 4 | Satisfactory | GAS SCRUBBER, PROPANE TANK, CHEMICAL TANK W/CONTAINMENT, SOLAR POWERED CATHOTIC RECTIFIER. | | |
| Pump Jack | 1 | Satisfactory | 160 TORQEMASTER | | |
| Prime Mover | 1 | Satisfactory | C-96 ARROW GAS ENGINE | | |

| Venting: | | |
|-----------------|--|--|
| Yes/No | Comment | |
| NO | BACK PRESSURE REGULATOR SETUP ON CASING. | |

| Flaring: | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 208598

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/U/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/U/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 208598 Type: WELL API Number: 017-07533 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Inspector Name: QUINT, CRAIG

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Inspector Name: QUINT, CRAIG

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started:

Date Final Reclamation Completed:

Final Land Use: RANGELAND

Reminder:

Comment:

Well plugged

Pit mouse/rat holes, cellars backfilled

Debris removed

No disturbance /Location never built

Access Roads Regraded

Contoured

Culverts removed

Gravel removed

Location and associated production facilities reclaimed

Locations, facilities, roads, recontoured

Compaction alleviation

Dust and erosion control

Non cropland: Revegetated 80%

Cropland: perennial forage

Weeds present

Subsidence

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Compaction | Pass | MHSP | Pass | |

S/U/V: Satisfactory

Corrective Date:

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT