

FORM

42

Rev
03/12

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

Document Number:

400574305

NOTICE OF NOTIFICATION

Entity Information

OGCC Operator Number: 96850 Contact Person: Lynn Cass
Company Name: WPX ENERGY ROCKY MOUNTAIN LLC Phone: (970) 285-9377
Address: 1001 17TH STREET - SUITE #1200 Fax: ()
City: DENVER State: CO Zip: 80202 Email: Lynn.Cass@wpxenergy.com
API #: 05 - 045 - 11021 - 00 Facility ID: Location ID:
Facility Name: AP 34-14-696
Sec: 14 Twp: 6S Range: 96W QtrQtr: SWSE Lat: 39.516215 Long: -108.073687

NOTICE OF INSPECTION CORRECTIVE ACTIONS PERFORMED

Corrective Actions required by field inspection document # 663902800 have been performed on 03/10/2014
Site is ready for re-inspection.

This form must be signed by an authorized agent of the entity making assertion.

I certify under penalty of perjury that this report has been examined by me and to the best of my knowledge is true, correct and complete.

Print Name: Lynn Cass Email: Lynn.Cass@wpxenergy.com
Signature: Lynn Cass Title: Drlg. Supt. Date:

Note:

No API # available for
the conductor that was closed. No
well was permitted.

Inspector Name: LONGWORTH, MIKE

Comp 3-7-14

A-406301050

FORM
INSPRev
05/11

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Inspection Date:

02/20/2014

Document Number:

663902800

Overall Inspection:

Unsatisfactory

FIELD INSPECTION FORM

Location Identifier Facility ID Loc ID Inspector Name: On-Site Inspection ☐
 335089 335089 LONGWORTH, MIKE 2A Doc Num: _____

Operator Information:

OGCC Operator Number:

Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC

Address: 1001 17TH STREET - SUITE #1200

City: DENVER State: CO Zip: 80202

☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Gardner, Michael	970/285-9377 ext. 2760	Michael.Gardner@WPXEnergy.com	Principal Environmental Specialist
Kellerby, Shaun		shaun.kellerby@state.co.us	
Moss, Brad	(970) 285-9377	Brad.Moss@WPXEnergy.com	Production foreman

Compliance Summary:

QtrQtr: SWSE Sec: 14 Twp: 6S Range: 96W

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279346	WELL	PR	01/30/2006	GW	045-11021	AP 34-14-696 <i>pad</i>	PR <input checked="" type="checkbox"/>
279378	WELL	PR	01/30/2006	GW	045-11026	AP 24-14-696	PR <input checked="" type="checkbox"/>
285345	WELL	PR	06/26/2006	GW	045-12451	AP 21-23-696	PR <input checked="" type="checkbox"/>
285346	WELL	PR	06/26/2006	GW	045-12450	AP 31-23-696	PR <input checked="" type="checkbox"/>
285347	WELL	PR	11/14/2006	GW	045-12449	AP 334-14-696	PR <input checked="" type="checkbox"/>
285348	WELL	PR	06/26/2006	GW	045-12448	AP 434-14-696	PR <input checked="" type="checkbox"/>
285349	WELL	PR	06/26/2006	GW	045-12447	AP 534-14-696	PR <input checked="" type="checkbox"/>
292781	WELL	PR	06/02/2009	GW	045-14787	AP 444-14-696	PR <input checked="" type="checkbox"/>
292782	WELL	PR	06/24/2010	GW	045-14786	AP 331-23-696	PR <input checked="" type="checkbox"/>
292783	WELL	PR	06/24/2010	GW	045-14785	AP 543-14-696	PR <input checked="" type="checkbox"/>
292784	WELL	PR	06/24/2010	OW	045-14784	AP 344-14-696	PR <input checked="" type="checkbox"/>
292785	WELL	PR	11/01/2013	GW	045-14783	AP 544-14-696	PR <input checked="" type="checkbox"/>
292786	WELL	PR	11/01/2013	GW	045-14782	AP 443-14-696	PR <input checked="" type="checkbox"/>
292787	WELL	PR	06/24/2010	GW	045-14781	AP 524-14-696	PR <input checked="" type="checkbox"/>
292788	WELL	PR	06/24/2010	GW	045-14780	AP 321-23-696	PR <input checked="" type="checkbox"/>
292789	WELL	PR	06/24/2001	GW	045-14779	AP 441-23-696	PR <input checked="" type="checkbox"/>
292790	WELL	PR	12/01/2011	GW	045-14778	AP 41-23-696	PR <input checked="" type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____ CA _____ CA Date _____
Waste Material Onsite? Pass CM _____ CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____ CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Fail CM open cellar and conductor CA Close cellar and conductor CA Date 03/21/2014
Guy line anchors removed? _____ CM _____ CA _____ CA Date _____
Guy line anchors marked? Pass CM _____ CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: Continue seeding of reclaimed areas

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Packing Slip 303803509 Repeat Printout



Customer PO	Sales Order 12702908	Shipment 808649581	Packing Slip	**** THIS IS NOT AN INVOICE DO NOT PAY FROM THIS DOCUMENT	Date: 03/07/2014
<u>Bill to</u> WPX ENERGY ROCKY MOUNTAIN, LLC EDI 3555 County Road 215 Parachute CO 81635		<u>Ship To</u> WPX ENERGY ROCKY MOUNTAIN, LLC Garfield Co/OCL PARACHUTE CO 81635		<u>Interim Ship To</u>	
AFE NUMBER: . JOB (PROJECT) #: . OTHER LEASES: DRILLING MAINTENANCE: .		ROUTING CODE: NKEPPARACH LOCATION #: PARACHUTE MAILBOX ORDER CONTACT: SCOTT MEADE NEW CONSTRUCTION: .		INTERNAL CUSTOMER #: . LEASES: . CUSTOMER SUPERVISOR: .	

Item	Material	Description	Qty	UM
120	61492	CEMENT QUIKRETE 80 LB BAG	8	EA
	AFE NUMBER: WT 15442		INTERNAL CUSTOMER #: JASON REED/ FMI	
	LEASES: AP 34-14 PAD		JOB (PROJECT) #: 03/07/14	
130	625287	DSC MTL 17-3/4 IN X 1/4 IN CIRCLE / ONEAL	2	EA
	AFE NUMBER: WT 15442		INTERNAL CUSTOMER #: JASON REED/ FMI	
	LEASES: AP 34-14 PAD		JOB (PROJECT) #: 03/07/14	

Subject to Terms on Back Payment Terms: Net 30 Days Delivery Terms: FOB SHIPPING POINT Currency: USD

Document 808649581 08:53:51 03/07/2014 Authorized
Customer Unavailable jason reed rg

Jason Reed

Questions: DNOW L.P. 3555 COUNTY ROAD 215 PARACHUTE CO 81635 Phone: 970-285-2217

** HAZARDOUS MATERIAL D.O.T. 24 HOUR EMERGENCY RESPONSE NUMBER: 1-888-298-2344 (ACCESS CODE/CONTRACT # 333386)**

We want to hear from you! Please send customer service comments and questions to ds-customer.priority1@nov.com