

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

04/16/2014

Document Number:

671101264

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

|                     |             |        |                 |  |
|---------------------|-------------|--------|-----------------|--|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection                         |
|                     | 249020      | 336632 | MONTOYA, JOHN   | <input type="checkbox"/> 2A Doc Num: _____ |

**Operator Information:**

OGCC Operator Number:

Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name   | Phone        | Email                       | Comment    |
|----------------|--------------|-----------------------------|------------|
| Pavelka, Linda | 303-506-4592 | LPavelka@nobleenergyinc.com |            |
| Fogel, Heather | 970-304-5168 | hfogel@nobleenergyinc.com   | Regulatory |

**Compliance Summary:**QtrQtr: SWNW Sec: 5 Twp: 3N Range: 66W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 06/25/2012 | 667600472 | PR         | PR          | Unsatisfactory               |          |                | No              |
| 06/06/2005 | 200071767 | PR         | PR          | Satisfactory                 |          | Pass           | No              |
| 05/20/2005 | 200075487 | PR         | PR          | Satisfactory                 |          | Pass           | No              |
| 04/27/1998 | 500174132 | PR         | PR          |                              |          |                |                 |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|-------------------------------------|
| 249018      | WELL | PR     | 06/16/1993  | OW         | 123-16820 | UPRC FEDERAL 5-3K | PR          | <input checked="" type="checkbox"/> |
| 249019      | WELL | PA     | 08/05/2003  | OW         | 123-16821 | UPRC 5-4K         | PA          | <input type="checkbox"/>            |
| 249020      | WELL | PR     | 10/24/2006  | GW         | 123-16822 | UPRC FEDERAL 5-5K | PR          | <input checked="" type="checkbox"/> |
| 249021      | WELL | PR     | 04/11/2006  | OW         | 123-16823 | UPRC FEDERAL 5-6K | PR          | <input checked="" type="checkbox"/> |

**Equipment:****Location Inventory**

|                             |                        |                     |                         |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____     | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____  | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____      | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____      | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

| <b>Signs/Marker:</b> |                             |         |                   |         |
|----------------------|-----------------------------|---------|-------------------|---------|
| Type                 | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD             | Satisfactory                |         |                   |         |

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Spills:</b> |      |        |                   |         |
|----------------|------|--------|-------------------|---------|
| Type           | Area | Volume | Corrective action | CA Date |

☐ Multiple Spills and Releases?

| <b>Equipment:</b> |   |                             |         |                   |         |
|-------------------|---|-----------------------------|---------|-------------------|---------|
| Type              | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Plunger Lift      | 3 | Satisfactory                |         |                   |         |

| <b>Venting:</b> |         |  |
|-----------------|---------|--|
| Yes/No          | Comment |  |
|                 |         |  |

| <b>Flaring:</b> |                             |         |                   |         |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type            | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|                 |                             |         |                   |         |

**Predrill**

Location ID: 249020

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/U/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/U/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 249018 Type: WELL API Number: 123-16820 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Facility ID: 249020 Type: WELL API Number: 123-16822 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Facility ID: 249021 Type: WELL API Number: 123-16823 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Inspector Name: MONTOYA, JOHN

Production areas have been stabilized? Pass

Segregated soils have been replaced? Pass

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced Pass

Recontoured Pass

Perennial forage re-established Pass

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? P

Comment: \_\_\_\_\_

Overall Interim Reclamation Pass

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

S/U/V: Satisfactory

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits: ☐ NO SURFACE INDICATION OF PIT