

API: 123_20472

06/12/2014 Site Pictures



View of reclaimed pad



Inside Transect Beginning Facing South East



Inside Transect Midpoint ground cover



Inside Transect Midpoint Facing North East



Inside Transect Midpoint Facing South West



06.12.2014 12:15

Inside Transect End view Facing North West



Outside Transect Beginning Facing North



Outside Transect Midpoint groundcover



Outside Transect Midpoint West



Outside Transect Midpoint Facing East



06.12.2014 12:46

Outside Transect End view Facing South