

Excavation Activities



Photo No 4:

Description: Front end loader scraping the surface of the contaminated area.



Photo No 5:

Description: Personnel digging by hand to avoid contact with pipeline.



Photo No 6:

Description: Another view of the site being worked on. Front end loader scraping the surface and personnel digging by hand.

Final View – Post Excavation & Soil Samples



Photo No 7:

Description: View of the post excavation site. Pink flags mark grab sample locations for composite soil sample.

Note: The deeper trench that was dug by hand to avoid contact with the pipeline.



Photo No 8:

Description: Another view of the post excavation site with meter run in background.

Contamination Pile



Photo No 9:

Description: The contaminated spoils pile.



Photo No 10:

Description: Closeup of the contaminated spoils pile.

Background Sample



Photo No 11:

Description: The background sample location.

Note: Pink flag in the middle of the photo is the background sample location.