FORM INSP Rev

05/11

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

ΕT OE ES Inspection Date:

11/04/2014

FIELD INSPECTION FORM									Doc	ument Numb			
Location	Facility ID L	oc ID	Inspector Name:			On-Site Inspection					673707831 Overall Inspection:		
Identifier		36792 Sherman, Susan				2A Doc Num:				_	TION REQU		
Operator I	nformation:												
OGCC Operator Number:10112 THIS IS A FOLLOW									OLLOW U	JP INS	SPECTION		
Name of O	perator: FOUND	DATION EN	TION ENERGY MANAGEMEN				NT LLC X			FOLLOW UP INSPECTION REQUIRED			
Address:	16000 DALLAS I	PARKWAY	#875						NO FOLLO	W UP INS	PECT	ION REQUIF	RED
City:	DALLAS	State:	T.	X	7	Zip: 752	48-	X				FORM 42 WH RE COMPLE	
	<i>D,</i> (22, 10								OOKKLOTI	VE NOTIC	,1 10 / 1	NE OOM EE	.,,,,
	formation:												
Contact Na						nail			Comment				
Eisterhold,		(918) 585-1650 regu X212 com			latory@foundationenergy.								
Compliand	ce Summary:												
QtrQtr: S	BESE	Sec:	2		Twp	: 1N		Range	e: 45W				
Insp. Date Doc Num		Insp.	Insp. Type Insp S		status		atisfactory ion Required		PA P/F/I	Pas/Fa (P/F)	il	Violation (Y/N)	
04/03/2007	04/03/2007 200108579		PR F		R SAT		TISFACTORY			Pass		No	
09/23/2005 200077579		9 PF	PR		WO		ACTION REQUIR			Fail		No	
Inspector C	Comment:												
Related F													
Facility ID Type		Status				ell Class	API Num		Facility Name			Insp Status	
279312 WELL		PR	PR 10/06/2005		G	GW 125-094		423	23 WAKEFIELD 44-2			PR	×
Equipmer	nt:				Loca	ation Invento	ory						
Special	Purpose Pits:	Drilling Pits:				Wells			:: Production Pits:				
Condensate Tanks:		Water Tanks				: Separators			: Electric Motors:				
Gas or Diesel Mortors:		Cavity Pumps:				LACT Unit			: Pump Jacks:				
Electric Generators:		Gas Pipeline:				Oil Pipeline			e: Water Pipeline:				
Gas Compressors:		VOC Combustor:				Oil Tanks			s: Dehydrator Units:				
Multi-Well Pits:		Pigging Station:				Flare			: Fuel Tanks:				
						<u>Location</u>	<u>on</u>						
Signs/Mark	<u>cer:</u>												
Туре		Satisfactory/Action Required			Comment Co			orrective Action			CA Date		
WELLHEA	\D	SATISFACTORY											

Inspector Name: Sherman, Susan OTHER SATISFACTORY lease sign at road Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: Comment: Corrective Action: **Good Housekeeping:** Type Satisfactory/Action Comment Corrective Action **CA Date** Required **ACTION REQUIRED WEEDS** Weeds on well Control weeds. 12/08/2014 location (see attached photo). Spills: Area **CA** Date Type Volume Corrective action Multilple Spills and Releases? Fencing/: Type Satisfactory/Action Comment Corrective Action **CA Date** Required **WELLHEAD** SATISFACTORY steel panels **PUMP JACK** SATISFACTORY steel panels **Equipment:** Satisfactory/Action Type Comment Corrective Action **CA Date** Required Prime Mover 1 SATISFACTORY electric Vertical Separator SATISFACTORY Gas Meter Run SATISFACTORY Ancillary equipment 2 SATISFACTORY electric panel, telemetry Gas Meter Run SATISFACTORY Pump Jack SATISFACTORY 1 **Facilities:** New Tank Tank ID: Contents # Capacity SE GPS Type COMPRESSOR STATION S/A/V: Comment: Republican Corrective Action: Corrective Date: **Paint** Condition Other (Content) Other (Capacity) Other (Type) **Berms** Capacity Permeability (Wall) Permeability (Base) Maintenance Type Corrective Action Corrective Date Comment

Inspector Name: Sherman, Susan Venting: Comment Yes/No Flaring: Satisfactory/Action Required Comment Type Corrective Action CA Date **Predrill** Location ID: 279312 Site Preparation: Pads: Soil Stockpile: Lease Road Adeq.: <u>S/A/V</u>: Date: CDP Num.: Corrective Action: Form 2A COAs: Comment: S/A/V: Date: CA: Wildlife BMPs: <u>S/A/V</u>: Comment: <u>CA</u>: Date: Stormwater: Comment: Staking: On Site Inspection (305): Surface Owner Contact Information: Name: Address: Phone Number: Cell Phone: Operator Rep. Contact Information: Landman Name: Phone Number: Date Onsite Request Received: Date of Rule 306 Consultation: Request LGD Attendance: LGD Contact Information: Phone Number: Agreed to Attend: Summary of Landowner Issues: Summary of Operator Response to Landowner Issues: Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment: <u>Facility</u> Type: Facility ID: 279312 WELL 125-09423 PR API Number: Insp. Status: Status:

Producing Well

Comment: Apr 2014 last reported production data.

309. COGCC Form 7. OPERATOR'S MONTHLY REPORT OF OPERATIONS

a. Operators shall report all existing oil and gas wells that are not plugged and abandoned on the Operator's Monthly Report of Operations, Form 7, within 45 days after the end of each month. A well must be reported every month from the month that it is spud until it has been reported for one month as abandoned. Each formation that is completed in a well shall be reported every month from the time that it is completed until it has been abandoned and reported for one month as abandoned. All information required by the form shall be reported, including all fluids produced during the initial testing and completion of the well.

Environmental					
Spills/Releases:					
ype of Spill: Description: Estimated Spill Volume:					
Comment:					
Corrective Action:	Date:				
Reportable: GPS: Lat Lor	ng				
Proximity to Surface Water: Depth to Ground Water:					
Water Well:	Long				
DWR Receipt Num: Owner Name: GPS :					
Field Parameters:					
Sample Location:					
Emission Control Burner (ECB):					
Emission Control Burner (ECB): Comment:					
Pilot: Wildlife Protection Devices (fired vessels):					
Reclamation - Storm Water - Pit					
Interim Reclamation:					
Date Interim Reclamation Started: Date Interim Reclamation Co	ompleted:				
Land Use:					
Comment: CRP					
1003a. Debris removed? Pass CM					
	CA Date				
Waste Material Onsite? Pass CM					
	CA Date				
CA					
Pit callare rat holes and other hores closed? Pass CM					
CA					
Guy line anchore removed? CM					
CA					
Guy line anchors marked? CM					
CA	CA Date				

Inspector Name: Sherman, Susan 1003b. Area no longer in use? Pass Production areas stabilized? Pass 1003c. Compacted areas have been cross ripped? Subsidence over on drill pit? 1003d. Drilling pit closed? Pass Cuttings management: 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass Production areas have been stabilized? Pass Segregated soils have been replaced? Pass RESTORATION AND REVEGETATION Cropland Top soil replaced Pass Recontoured Pass Perennial forage re-established In Non-Cropland Recontoured 80% Revegetation Top soil replaced 1003 f. Weeds Noxious weeds? Comment: Overall Interim Reclamation In Process Final Reclamation/ Abandoned Location: Date Final Reclamation Started: Date Final Reclamation Completed: Final Land Use: Reminder: Comment: Well plugged Pit mouse/rat holes, cellars backfilled Debris removed No disturbance /Location never built Contoured Culverts removed Access Roads Regraded Gravel removed Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____ Compaction alleviation Dust and erosion control Cropland: perennial forage Non cropland: Revegetated 80% Weeds present Comment: Corrective Action: Date Well Release on Active Location Overall Final Reclamation Multi-Well Location Storm Water: BMP Chemical BMPs Loc Erosion BMPs Lease BMP Lease Road Erosion Chemical BMP Comment Maintenance BMPs Maintenance Maintenance Gravel Pass Compaction Compaction Pass Pass Corrective Date: S/A/V: SATISFACTOR

Comment:

CA:

Pits: NO SURFACE INDICATION OF PIT

	COGCC Comments		
Comment		User	Date
Update production data.		ShermaSe	11/10/2014

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
673707837	Foundation Wakefield 44 2 lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3479645
673707838	Foundation Wakefield 44 2 well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3479656
673707839	Foundation Wakefield 44 2 wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3479657
673707840	Foundation Wakefield 44 2 well equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3479658
673707841	Foundation Wakefield 44 2 well weeds	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3479659
673707842	Foundation Wakefield 44 2 well equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3479660

Date Run: 11/10/2014 Doc [#673707831]

ACTION REQUIRED

ANY ACTION REQUIRED items listed on this report indicate that the oil and gas facility or the oil and gas operations listed on the report may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission ("COGCC") and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator's compliance with this Inspection Report is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **Corrective Action Deadline Date.** Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34 -60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)

Date Run: 11/10/2014 Doc [#673707831]