

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/12/2016

Document Number:

674003378

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	414931	327542	Carlile, Craig	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections
Avant, Paul	(720) 929-6457	Paul.Avant@Anadarko.com	All Inspections
, Reddy		luke.reddy@anadarko.com	

Compliance Summary:QtrQtr: NWNW Sec: 4 Twp: 3N Range: 66W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/10/2011	200295892	PR	PR	SATISFACTORY	I		No
03/16/2010	200235597	DG	DG	SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
247033	WELL	PR	03/12/2014	GW	123-14830	WEBBER 11-4	PR	<input checked="" type="checkbox"/>
414931	WELL	PR	06/12/2010	GW	123-30901	WEBBER 31-4	PR	<input checked="" type="checkbox"/>
414933	WELL	PR	06/18/2010	GW	123-30903	WEBBER 29-4	PR	<input checked="" type="checkbox"/>
415059	WELL	PR	06/11/2010	GW	123-30967	WEBBER 18-4	PR	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Inspector Name: Carlile, Craig

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>4</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: <u>4</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: <u>4</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>1</u>	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
BATTERY	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
SEPARATOR	SATISFACTORY			
TANK BATTERY	SATISFACTORY			
IGNITOR/COMBUST OR	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Equipment:

Type: Bird Protectors	# 3	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date: _____
Type: Horizontal Heated Separator	# 2	Satisfactory/Action Required:	SATISFACTORY
Comment			

Inspector Name: Carlile, Craig

Corrective Action		Date:
Type: Gas Meter Run	# 2	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:
Type: Plunger Lift	# 4	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:
Type: Emission Control Device	# 1	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date:

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	2	OTHER	STEEL AST	40.259130,-104.791480

S/AR	Comment:
Corrective Action:	Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) 3105 Bbl

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	

Corrective Action	Corrective Date
Comment	

Venting:

Yes/No
Comment

Flaring:

Type	Ignitor/Combustor	Satisfactory/Action Required	SATISFACTORY
Comment:			
Corrective Action:	Correct Action Date:		

Predrill

Location ID: 414931

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
Agency	caplank	Location is in a sensitive area because of proximity to a domestic water well; therefore either a lined drilling pit or closed loop system is required.	12/11/2009

S/AR: _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 247033 Type: WELL API Number: 123-14830 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Plumbed to surface.

CA: _____

CA Date: _____

Facility ID: 414931 Type: WELL API Number: 123-30901 Status: PR Insp. Status: PR

Facility ID: 414933 Type: WELL API Number: 123-30903 Status: PR Insp. Status: PR

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

S/A/V: SATISFACTORY CA Date: _____

CA: _____

Comment: _____

BradenHead

Comment: Plumbed to surface.

CA: _____

CA Date: _____

Facility ID: 415059 Type: WELL API Number: 123-30967 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

S/A/V: SATISFACTORY CA Date: _____

CA: Signage indicating shut in for hz prep

Comment: _____

BradenHead

Comment: Plumbed to surface.

CA: _____

CA Date: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): Y

Comment: _____

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Interim Reclamation:**

Inspector Name: Carlile, Craig

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? In

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Inspector Name: Carlile, Craig

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine inspection.	carlilec	02/12/2016