

## Abandoned Location Inspection



**Photo 1.** Photo taken of PR well 001-08800.

## Abandoned Location Inspection



**Photo 2.** Photo taken of PR well 001-08800, confirming the AL status of 001-09600, 001-09599, and 001-09469. It appears 001-09600, 001-09599, and 001-09469 were never built at location. This is a well release on an active location.