



Photo#1: Over View of Location looking to South.



Photo#2: First Closed Access Road & or Pipeline to Adjacent Facilities, ran NE from main Access Road.





Photo#3: Second Closed Access Road & or Pipeline to Adjacent Facilities, ran NE out of Location.



Photo#4: Third Closed Access Road & or Pipeline at South end of Location.





Photo#5: Interim Reclamation on West side of Location.





Photo#6: Vegetation Monitoring site located in Interim Reclamation .