

697-2C pad location
Interim Reclamation - Revegetation

10/20/2011 grading and seeding began
11/01/2011 grading and seeding complete

Photos taken 5/21/2014



Southern fill slope



Fill slope at southwestern corner of pad



Western fill slope



Western fill slope



Western fill slope



Western fill slope



Reclaimed area northwest of pad



Reclaimed area northwest of pad



Reclaimed area northwest of pad



Reclaimed area northwest of pad



View of cut slope on east side of pad



Top soil pile



Top soil pile



Top soil pile



Top soil pile