

# Test Report



May 13, 2016

Client: NGL Water Solutions DJ

Project: C2C

Lab ID: 5137

Date Samples Received: 5/12/2016

Number of Samples: 2

Sample Condition: Samples arrived intact and in appropriate sample containers

Sample Temperature: Samples arrived within the acceptable temperature range as specified in the test method

Comments:

Thank you for allowing eAnalytics Laboratory to provide laboratory services for you.

A handwritten signature in black ink, appearing to read "Chris Dieken".

Christopher Dieken  
Quality Assurance Manager

A handwritten signature in black ink, appearing to read "Todd Rhea".

Todd Rhea  
Laboratory Manager

**eAnalytics Laboratory**

4130 Clydesdale Parkway Loveland CO 80538

## Chain of Custody

**eANALYTICS**  
LABORATORY

### Chain of Custody For

[illegible]

Lab ID # 5137

**eAnalytics Laboratory**  
4130 Clydesdale Parkway Loveland CO 80538  
(970) 667-6975

Page 1 of 1

**eAnalytics Laboratory**  
4130 Clydesdale Parkway Loveland CO 80538

**eANALYTICS**  
LABORATORY

Client: NGL Water Solutions DJ

Lab ID: 5137

Project: C2C

Analysis: Total Dissolved Solids  
Total Suspended SolidsMethod: EPA160.1  
EPA160.2

Sample Name	TDS	TSS	Date	Date	Lab ID
	mg/L	mg/L	Sampled	Analyzed	
Extraction Troutd 6	35840	9200	05/11/16	05/12/16	5137 1
PDC Olander U-14-14	1548	22450	05/11/16	05/12/16	5137 2

**eAnalytics Laboratory**

4130 Clydesdale Parkway Loveland CO 80538