BP L48 San Juan

Form Information

Form Name: Submitter Name: Submission Date: Server Receive Date: Reference Number: Location: Compliance Follow Up Form Aaron Easley (aaroneasley) Nov 18, 2016 4:45:39 PM MST Nov 18, 2016 4:46:19 PM MST 20161118-1851251052 Unknown Location

Information

Name
Date
Well Name
API Number
Select State
Work type
Action Complete
Picture South to North

aaroneasley
Nov 18, 2016
COLVIN, BRUCE GAS UNIT A 1
50670783400
Colorado
COGCC Inspection AR
Clean Up Weed Debris



Picture East to West



Completed work description

Manually removed thistle from well site. Thistle rosettes need to be chemically treated next spring.