

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2016

Submitted Date:

12/07/2016

Document Number:

678800172**FIELD INSPECTION FORM**

Loc ID 410504	Inspector Name: LEONARD, MIKE	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 3 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:			
OGCC Operator Number: <u>60890</u>			
Name of Operator: <u>MOUNTAIN PETROLEUM CORP</u>			
Address: <u>1801 BROADWAY STE 1250</u>			
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>	

Contact Information:

Contact Name	Phone	Email	Comment
,		regulatory@foundationenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252293	WELL	PA	11/24/2008	GW	125-06163	SMITH-EKBERG 1-4	PA

General Comment:

This inspection is being entered as a follow up to inspection document #668600214. This document stated well was plugged and abandoned, however final overall reclamation release was not granted due to gas meter runs being in place. Foundation Energy Management has taken ownership of the gas meter runs on location and will be responsible for final reclamation of the location when equipment is no longer in use.

Inspected Facilities									
Facility ID:	252293	Type:	WELL	API Number:	125-06163	Status:	PA	Insp. Status:	PA

--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: This inspection is being entered as a follow up to inspection document #668600214. This document stated well was plugged and abandoned, however final overall reclamation release was not granted due to gas meter runs being in place. Foundation Energy Management has taken ownership of the gas meter runs on location and will be responsible for final reclamation of the location when equipment is no longer in use.

Corrective Action: <input type="text"/>		Date <input type="text"/>
Overall Final Reclamation	Pass	Well Release on Active Location <input checked="" type="checkbox"/>
		Multi-Well Location <input type="checkbox"/>