Inspector Name: LONGWORTH, MIKE

FORM INSP

X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date: 12/22/2016

Submitted Date: 12/22/2016

Document Number: 674703488

FIELD INSPECTION FORM

| Loc ID | Inspector Nam | Inspector Name: | | On-Site Inspection | | Statu | ıs Summary: |
|------------|--------------------|-----------------|-----------|--------------------|----------------------|-------|--|
| 335220 | LONGWORTH | I, MIKE | 2A Do | oc Num | : | T | THIS IS A FOLLOW UP INSPECTION |
| Operator | Information: | | _ | | | F | OLLOW UP INSPECTION REQUIRED |
| OGCC Op | perator Number: | 96850 | | | | X | IO FOLLOW UP INSPECTION REQUIRED |
| Name of C | Dperator: TEP ROCK | Y MOUNTAII | Findings: | | | | |
| Address: | PO BOX 370 | | | | | 6 | Number of Comments Number of Corrective Actions |
| City: | PARACHUTE | State: | СО | Zip: | 81635 | | orrective Action Response Requested |
| Contact II | nformation: | | | | | • | |
| Contact N | Name | Phone | Eı | mail | | | Comment |
| Inspectio | n, Terra TEP | 970-263 | | OGCC raep.c | InspectionRepo om | rts@t | |

| Inspected Facilities: | | | | | | | | |
|-----------------------|---------------------|-------------------------------------|--|--|--|---|--|--|
| Туре | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | | |
| WELL | PR | 09/03/1987 | GW | 045-06541 | MOBIL W-17-27 | PR | | |
| WELL | PR | 01/20/2004 | GW | 045-09090 | PA 34-27 | PR | | |
| WELL | PR | 03/30/2005 | GW | 045-10276 | PA 534-27 | PR | | |
| WELL | PR | 04/26/2005 | GW | 045-10277 | PA 434-27 | PR | | |
| | Type WELL WELL WELL | Type Status WELL PR WELL PR WELL PR | Type Status Status Date WELL PR 09/03/1987 WELL PR 01/20/2004 WELL PR 03/30/2005 | Type Status Status Date Well Class WELL PR 09/03/1987 GW WELL PR 01/20/2004 GW WELL PR 03/30/2005 GW | Type Status Status Date Well Class API Num WELL PR 09/03/1987 GW 045-06541 WELL PR 01/20/2004 GW 045-09090 WELL PR 03/30/2005 GW 045-10276 | Type Status Status Date Well Class API Num Facility Name WELL PR 09/03/1987 GW 045-06541 MOBIL W-17-27 WELL PR 01/20/2004 GW 045-09090 PA 34-27 WELL PR 03/30/2005 GW 045-10276 PA 534-27 | | |

General Comment:

Inspector Name: LONGWORTH, MIKE

| <u>Location</u> | | | | | | |
|--------------------------|-------------------|--------|------|-----------------|-------|---|
| Overall Good: 🔀 | | | | | | |
| Signs/Marker: | | | | | | |
| Туре | TANK LABELS/PLACA | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | Date | : | | |
| Туре | BATTERY | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date | : |
| Туре | WELLHEAD | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date | : |
| Туре | CONTAINERS | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date | : |
| Emergency Contact N | lumber: | | | | | |
| | 970-285-9377 | | | | = | |
| Corrective Action: | | | | | Date: | |
| Overall Good: 🔀 | | | | | | |
| Spills: | | | | | | |
| Туре | Area | Volume | | | | |
| In Containment: N | lo | | | | | |
| Comment: | | | | | | |
| Multilple Spills a | nd Releases? | | | | | |
| Fencing/: | | | | | | |
| Туре | SEPARATOR | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Туре | TANK BATTERY | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Туре | WELLHEAD | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Equipment: corrective da | | | | corrective date | | |
| Type: Gas Meter Run | | # 1 | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |
| Type: Plunger Lift | | # 3 | | | | |

Inspector Name: LONGWORTH, MIKE Comment: Corrective Action: Date: Type: Horizontal Heated Separator # 4 Comment: Corrective Action: Date: Type: Bird Protectors #2 Comment: Corrective Action: Date: Type: Ancillary equipment # 1 Comment: Chemical container at wells Corrective Action: Date: Tanks and Berms: SE GPS Contents Capacity Type Tank ID PRODUCED WATER **300 BBLS** STEEL AST Comment: Corrective Action: Date: **Paint** Condition Adequate Other (Content) Other (Capacity) Other (Type) Berms Permeability (Wall) Permeability (Base) Туре Capacity Maintenance Earth Walls Sufficent Adequate Base Sufficient Adequate Comment: Corrective Action: Date: Venting: Yes/No NO Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

| Inspector Name: LONGWORTH, MIKE | | | | | | | | | | | |
|---------------------------------|-----------|--------------|------|-------------|-----------|-----------|----|-----------------|----|--|--|
| Inspected Facilities | | | | | | | | | | | |
| Facility ID: | 210783 | Type: | WELL | API Number: | 045-06541 | Status: _ | PR | Insp. Status: | PR | | |
| | | | | Produc | ing Well | | | | | | |
| Co | omment: | Producing we | | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | | | |
| | | | | | | | | | | | |
| Facility ID: _ | 265918 | Type: | WELL | API Number: | 045-09090 | Status: _ | PR | Insp. Status: | PR | | |
| Producing Well | | | | | | | | | | | |
| Co | omment: | Producing we | ell | | | | | | | | |
| Corrective | e Action: | | | | | | | Date: | | | |
| | | | | | | | | | | | |
| Facility ID: _ | 273768 | Type: | WELL | API Number: | 045-10276 | Status: _ | PR | Insp. Status: | PR | | |
| Producing Well | | | | | | | | | | | |
| C | omment: | Producing we | ell | | | | | | | | |
| Corrective | e Action: | | | | | | | Date: | | | |
| | | | | | | | | | | | |
| Facility ID: _ | 273769 | Type: | WELL | API Number: | 045-10277 | Status: _ | PR | Insp. Status: _ | PR | | |
| Producing Well | | | | | | | | | | | |
| Comment: | | Producing we | ell | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

Inspector Name: LONGWORTH, MIKE

| Reclamation - Storm Water - Pit | | | | | | | | |
|---------------------------------|--------------------|----------------------------|--------------------------|--|-----------------------------|---------|--|--|
| Storm Water: | | | | | | | | |
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment | | |
| Berms | Pass | | | | | | | |
| Ditches | Pass | | | | | | | |
| Compaction | Pass | | | | | | | |
| | | | | Material Handling And Spill Prevention | Pass | | | |
| Gravel | Pass | | | | | | | |
| Seeding | Pass | | | | | | | |
| Comment: Corrective Action: | | | | | | | | |
| Pits: 🔀 NO S | SURFACE INDIC | CATION OF PIT | | | | | | |
| Attached Docume | ents | | | | | | | |
| You can go to CO | GCC Images (| https://cogcc.state.co. | us/weblink/) an | d search by doc | ument number: | | | |
| Document Num C 674703488 | | URL APPROVED http://ogco | | | | | | |
| | | | | | | | | |
| | | | | | | | | |