Inspector Na	ame: LONGWORT	,								
FORM			tate of Co					D N R		ion Date:
INSP	<sup>SP</sup> Oil and Gas Conservation Commission									<u>3/02/2017</u>
Rev X/15										ted Date: 03/02/2017
								ТМ		ent Number:
		FIELD	) INSPECT	ION FC	RM					574703692
Loc ID	Inspector Nam	ne:	On-Site I	Inspection			Statu	s Summary:		
416157	LONGWORTH	H, MIKE	2 <i>F</i>	A Doc Nun	n:		TI	HIS IS A FOLLOW UP	INSPEC	TION
Operator In	formation:						F(	OLLOW UP INSPECTION	ON REQ	UIRED
OGCC Ope	rator Number:	10456					XN	O FOLLOW UP INSPE	CTION F	REQUIRED
Name of Op	erator: CAERUS F	PICEANCI	E LLC				<u>Findi</u>	ngs:		
Address: 1	001 17TH STREET	Г #1600				_	2	Number of Commen		
			<u> </u>	7:	00000	—	0	Number of Correctiv		
City:	DENVER	State:	CO	Zip:	80202	_	Co	prrective Action Response	Requeste	d
Contact Inf		D						<u> </u>		
Contact Na		Phor	ne	Email				Comment		
Janicek, Ja	ake			JJanice	k@caerusc	ollandga	as.c			
Elsener, G	arrett			garrett@caerusoilandgas			com			
McKee, Mi	chael			MMckee@caerusoilandga			s.co			
				m						
Inspected F		<u> </u>		NA7 11		<u> </u>				
Facility ID 448166	Type WELL	Status XX	Status Date 10/23/2016	vveii		PI Num	-	Facility Name Puckett 33C-26-697		Insp Status DG
General Co		**	10/23/2016		0.	45-2335	5	Puckett 33C-26-697		DG

Inspector Name: LONGWORTH, MIKE

			Location		
Overall Good: 😿					
Emergency Contact N	Number:				
Comment:					
Corrective Action:				Date	
Overall Good: 🔀					
<u>Spills:</u>					
Туре	Area	Volume			
In Containment:	No				
Comment:					
Multilple Spills a	and Releases?				
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
<u>Flaring:</u>					
Туре					
Comment:					
Corrective Action:				Date:	

Inspector Name: LONGWORTH, MIKE

	Location Construction	
Location ID: 41	6157 CDP:	
Comment:		
Corrective Action:		Date:
Form 2A COAs:		
	Notices are being received	
Corrective Action:		Date:
Wildlife BMPs:		
	Stormwater bmps are in place. No pit on location, using closed loop system.	
Corrective Action:		Date:
<u>Comment</u> :		
Corrective Action:		Date:
On Site Inspection		
<u>Surface Owner Con</u> Name:	Address:	
Phone Number:	Cell Phone:	
Operator Rep. Cont		
Landman Name:	Phone Number:	
Date Onsite Reques		
Request LGD Atten		
LGD Contact Inform		
Name:	Phone Number: Agreed to Attend:	
Summary of Landov	/ner Issues:	
Summary of Operat	or Response to Landowner Issues:	
Onsite Inspection M	emorandum Summarizing Discussions at Inspection as Attachment:	

Inspector Name: LONGWORTH, MIKE

	Inspected Facilities											
Facilit	ty ID:	448166	Туре:	WELL	API Nu	umber:	045-23355	Sta	tus:	XX	Insp. Status:	DG
						Well Dril	ling					
Rig:		ig Name:			Pusher/Rig				_			
		_			Ac	cess Sign	:		_			
Well (		ol Equipme										
		ripe Ram: _		Blind			-					
1		-		Test Pressure	e PSI:	Saf		ΈS				
Drill F Mana												
		Lined Pit:		Unlined	d Pit:		Closed Loc	op: YES		Semi-0	Closed Loop:	
	Ν	lulti-Well:		Disposal Lo	cation:				_			
	<u>(</u>	Comment:										
Co	orrectiv	e Action:									Date:	

Reclamation - Storm Water - Pit
---------------------------------

			Reclama	ation - Storm	water - Pit		
Storm Water:							
Loc Erosion BMPs	BMP Maintenance	Lease Road BMPs	Erosion	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass			+			-
	+	Ditches		Pass	+		-
Gravel	Pass				1		
		Compaction		Pass			
					Covering Materials	Pass	
		Culverts		Pass			
					Material Handling And Spill Prevention	Pass	
Comment	:						]
Corrective Action	:						Date:
Pits: 🔀 NO	SURFACE INDI	CATION OF P	- IT				
Attached Docum	<u>ients</u>						
You can go to CC	GCC Images (	https://cogco	<u></u>	us/weblink/) an	nd search by doc	ument number:	
Document Num	Description		URL				
	INSPECTION		http://ogco	cweblink.state.co	us/DownloadDocu	umentPDF.aspx?I	DocumentId=4089681
	SUBMITTED						

T