

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/07/2017

Submitted Date:

06/16/2017

Document Number:

687900023**FIELD INSPECTION FORM**

Loc ID 308844 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|---------------------------|-------------------------------|-----------------------------|
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| Trujillo, Irwin | 719-846-0272/719-859-2264 | irwin_trujillo@xtoenergy.com | Sr. Env. Tech., Raton Basin |
| Fitzgerald, Edie | 719-845-2108/719-859-1394 | Edie_Fitzgerald@xtoenergy.com | Env. Tech, Raton Basin |
| Harrison, Lyndon | 505-333-3100 | Lyndon_Harrison@xtoenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 283342 | WELL | PR | 01/12/2007 | GW | 071-08717 | GOLDEN EAGLE 19-15 | PR |

General Comment:

2017 Flowline NTO Inspection
 Shadowing Operator Pressure Testing Team
 XTO Team : Lyndon L. Harrison, Joseph Garcia, Carl Vialpando

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Flow Line | # 1 | | |
| Comment: | IN USE : 1 - 2" Fuel/Gas riser at Seperator (37.15355/-104.92671) | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | IN USE : 1 - 4" Casing line riser at wellhead (37.15356/-104.92658) | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | IN USE : 1 - 3" Tubing line riser at wellhead (37.15356/-104.92658) to discharge line. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 283342 Type: WELL API Number: 071-08717 Status: PR Insp. Status: PR

Flowline

| | | |
|----|-----------------|------------|
| #1 | Type: Well Site | 1 of Lines |
|----|-----------------|------------|

Flowline Description

Flowline Type: Well Site Size: 3" Material: Poly
 Variance: Yes Age: 10-15 Yrs Contents: Produced Water

Integrity Summary

Failures: Spills: No Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Material : Carbon Steel riser to Poly line. No Physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 10:50 am, P=30.5 psig, Time : 11:05 am, P=30.5 psig.

Corrective Action:

Date:

| | | |
|----|-----------------|------------|
| #2 | Type: Well Site | 1 of Lines |
|----|-----------------|------------|

Flowline Description

Flowline Type: Well Site Size: 4" Material: Poly
 Variance: No Age: 10-15 Yrs Contents: Natural Gas

Integrity Summary

Failures: Spills: No Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Yes Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Material : Carbon Steel riser to Poly line. No physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 11:11 am, P=2.0 psig, Time : 11:26 am, P=2.0 psig.

Corrective Action:

Date:

| | | |
|----|-----------------|------------|
| #3 | Type: Well Site | 1 of Lines |
|----|-----------------|------------|

Flowline Description

Flowline Type: Well Site Size: 2" Material: Poly
 Variance: No Age: 10-15 Yrs Contents: Natural Gas

Integrity Summary

Failures: Spills: No Repairs Made: No
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: Yes

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation

☒ 1102. Operations, Maintenance, and Repair

☐ 1103. Abandonment

Comment:

Material : Carbon Steel riser to Poly line. No Physical chart in the field, but XTO used a Crystal Digital Pressure Guage - AMETEK xpzi 5,000 psig (To record pressures). Time : 11:28 am, P=2.0 psig, Time : 11:43 am, P=2.0 psig.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

| | | | |
|---------|-------------|------------|-----------------|
| Permit: | Facility ID | Permit Num | Expiration Date |
| | 292628 | 2059140 | |